

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

EMPEROR LEASING PTE LTD
1 KUNG CHONG ROAD
SINGAPORE 159139

Contact : 65436968, 80639739 92322984

TAX INVOICE

Repair Code : CLM18471

Date in : 20/11/2024

Vehicle Num. : SNA960H

Model : TOYOTA NOAH HYBRID 7-SEATER 1.8X CVT

Chassis/Eng# : ZWR800487522/2ZR2L53230

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER / BR (Disassemble) /	1	843.80	843.80 ✓
FRONT BUMPER LH FOG LAMP ? X nn	1	329.00	329.00
FRONT BUMPER SIDE RETAINER L/R ? / BR	1	149.10	298.20 149.10 ✓
FRONT LH FENDER X R	1	1604.50	1,604.50
FRONT LH FENDER INNER SHIELD X nn	1	262.10	262.10
FRONT LH HEADLAMP / (H)	1	5238.50	5,238.50 3384 ✓
FRONT LH KNUCKLE ARM X nn	1	927.80	927.80
FRONT LH KNUCKLE ARM BEARING X nn	1	325.40	325.40
Subtotal before discount		4376.90	9,829.30
Percentage discount 25%		25%	2,457.33
		3282.67	
Sub-total 1			7,371.98
FRONT BUMPER CLIPS - SET / PL	1	80.00	80.00 30
FRONT LH 205/55R16 TYRE X nn	1	400.00	400.00
FRONT LH FENDER INNER SHIELD CLIPS - SET X nn	1	50.00	50.00
FRONT LH SPORT RIM X nn	1	900.00	900.00
Subtotal before discount			1,430.00
Percentage discount 0%		30	0.00
Sub-total 2			1,430.00
Parts-total			8,801.98

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

EMPEROR LEASING PTE LTD
 1 KUNG CHONG ROAD
 SINGAPORE 159139

Contact : 65436968, 80639739 92322984

TAX INVOICE

Repair Code : CLM18471
 Date in : 20/11/2024
 Vehicle Num. : SNA960H
 Model : TOYOTA NOAH HYBRID 7-SEATER 1.8X CVT
 Chassis/Eng# : ZWR800487522/2ZR2L53230

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	30	80.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	X	300.00
To road test driving, check and resetting wheel alignments system.		80.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	400	900.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	300	700.00
To apply anti-rust chemical on repaired and replaced panel.	30	100.00
Labour Total	760	2,160.00
Parts & Labour Total		10,961.98

*** This is a computer-generated document which requires no signature.***

page 2

STEW (LKK)
 10/12/24, 11-30 am
 m IL
 L/S
 L AL M
 3 days

4072.67

L/S - 3258.13
 = 3250

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: