



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBG 8414B

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TAILGATE	DENTED	\$1,585.90	\$1,585.90
1	TAILGATE STICKER 'TOYOTA'	NECESSARY	\$190.60	\$190.60
1	TAILGATE STICKER 'DYNA'	NECESSARY	\$68.60	\$68.60
1	TAILGATE LOWER MEMBER	TO REPAIR SEE LABOUR	\$511.60	\$0.00
1	TAILLAMP -LH	CRACKED	\$291.35	\$291.35
1	TAILLAMP PANEL -LH	TO REPAIR SEE LABOUR	\$210.50	\$0.00
1	SIDEGATE LOCK HINGE -LH	TO REPAIR SEE LABOUR	\$210.55	\$0.00
	LESS 25.00% DISCOUNT		(\$767.28)	(\$534.11)
			\$2,301.82	\$1,602.34

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR STICKER '70KM/H' (SN)	NECESSARY	\$10.00	\$10.00
1	REAR STICKER '6 PAX' (SN)	NECESSARY	\$10.00	\$10.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	\$280.00	\$200.00
			\$300.00	\$220.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK REAR ELECTRICAL WIRING		\$50.00	\$30.00
	TO TUFF KOTE		\$60.00	\$20.00
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		\$700.00	\$400.00
	TO PANEL BEAT, CUT, WELD, REMOVE & PEPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE LOWER MEMBER, TAILLAMP PANEL -LH AND SIDEGATE LOCK HINGE -LH		\$600.00	\$400.00
			\$1,410.00	\$850.00

GRAND TOTAL			\$4,011.82	\$2,672.34
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$2,150.00

Report Ref No: CS/INC24120125/Enh3m4

TOTAL FOR SPARE PARTS: \$ 2,601.82 \$ 1,822.34
TOTAL FOR LABOUR : \$ 1,410.00 \$ 850.00
TOTAL REPAIR COST: \$ 4,011.82 \$ 2,672.34



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.