



ASSESSMENT FOR REPAIR : JWW1686

YAMAHA MT-15

COE EXPIRY :

Lump Sum / Part by Part

not Authored
in
memo
12/6/24
L/S \$1380
Amphibious
3 days

Qty	Description	Repairer's Estimate	1st Survey	Repair Survey	Final Survey
1	FRONT FENDER	327.00	Cut ✓		
1	RH - MIRROR	60.00	Cut ✓		
1	HANDLE BAR	60.00	Beet ✓		
1	RH - LEVER	28.00	Cut ✓		
1	RH - BAR END	71.00	Cut ✓		
1	BRAKE PEDAL	55.00	Cut ✓		
1	RH - PILLION FOOTPEG	28.00	Cut ✓		
1	EXHAUST PROTECTOR	55.00	Cut ✓		
1	EXHAUST END CAP	65.00	Cut ✓		
1	RH - AIR INTAKE COWL	327.00	Cut ✓		
1	RH - AIR INTAKE COWL STICKER	109.00	Net ✓		
1	RH - TANK COWL (GREY)	327.00	17X		
1	RH - TAIL COWL	272.50	Cut ✓		
1	RH - TAIL COWL STICKER	55.00	Net ✓		
1	GEAR PEDAL	66.00	17X		
1	RH - FRONT SIGNAL LIGHT	78.00	Cut ✓		
		1,983.50			

Special Nett Items

STEERING CONE & BEARING
FRONT FORK ALIGNMENT
WHEEL ALIGNMENT
FRAME ALIGNMENT

130.00	17X		
230.00	17X		
130.00	17X		
210.00	17X		
700.00			

Total Parts

2,683.50

Labour Charges

1 Workmanship to renew damage parts & areas
\$100 per days X 4 days

400.00
400.00

300

Total Parts & Labours Concluded

3,083.50

1-159050
102
143145
300
173145

SANFU MOTOR PTE LTD
Company Reg No.: 200612487G
1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883
Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010 by Repairer
Email: sanfumotor0243@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:
Date: