

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 24.06.2024

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SJK9171D
MODEL : HONDA FIT
DATE OF ACCIDENT : 24.06.2024
TIME OF ACCIDENT : 07:40 HOURS

2008 Nov
GE61117210
Daphne.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Disbled</i>	1	\$ 530.50	\$ 530.50
2	FRONT BUMPER TOW COVER <i>Deled</i>	1	\$ 15.10	\$ 15.10
3	FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 268.80	\$ 268.80
4	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 20.40	\$ 40.80
5	FRONT BUMPER LOWER GRILLE <i>Crashed</i>	1	\$ 171.60	\$ 171.60
6	FRONT GRILLE <i>Deled</i>	1	\$ 199.70	\$ 199.70
7	FRONT GRILLE LOGO <i>new</i>	1	\$ 23.40	\$ 23.40
8	HEADLAMP <i>Crashed</i>	2	\$ 529.50	\$ 1,059.00
9	HEADLAMP LOWER BRACKET <i>Crashed</i>	2	\$ 46.70	\$ 93.40
10	FRONT WIPER TANK <i>new</i>	1	\$ 98.00	\$ 98.00
11	FRONT WIPER TANK MOTOR <i>new</i>	1	\$ 79.60	\$ 79.60
12	BONNET <i>Buckled</i>	1	\$ 464.70	\$ 464.70
13	BONNET STAND CLIP <i>new</i>	1	\$ 12.00	\$ 12.00
14	BONNET HINGE <i>new</i>	2	\$ 62.00	\$ 124.00
15	BONNET WEATHER STRIP <i>new</i>	2	\$ 32.00	\$ 64.00
16	BONNET STOPPER <i>new</i>	2	\$ 15.00	\$ 30.00
17	BONNET LOCK <i>new</i>	1	\$ 76.50	\$ 76.50
18	FRONT SUPPORT PANEL <i>Buckled</i>	1	\$ 574.60	\$ 574.60
19	FRONT SUPPORT LOWER APRON PANEL <i>Repair</i>	1	\$ 385.60	\$ 385.60
20	AIR CON CONDENSER <i>Dented</i>	1	\$ 796.80	\$ 796.80
21	AIR CON CONDENSER MOUNTING RUBBER <i>new</i>	2	\$ 15.00	\$ 30.00

TO
VEHICLE NO
MODEL
DATE OF ACCIDENT
TIME OF ACCIDENT

: CHINA TAIPING MOTOR CLAIMS DEPTS
: SJK9171D
: HONDA FIT
: 24.06.2024
: 07:40 HOURS

22	AIR CON CONDENSER BRACEKT	2	\$ 15.00	\$ 30.00
23	AIR CON FAN MOTOR	1	\$ 264.10	\$ 264.10
24	AIR CON FAN COWLING	1	\$ 118.90	\$ 118.90
25	AIR CON PIPE	1	\$ 180.50	\$ 180.50
26	RADIATOR	1	\$ 1,207.60	\$ 1,207.60
27	RADIATOR TOP BRACKET	2	\$ 29.20	\$ 58.40
28	RADIATOR RUBBER MOUNTING	2	\$ 12.00	\$ 24.00
29	RADIATOR SPARE TANK	1	\$ 72.10	\$ 72.10
30	RADIATOR HOSE (UPPER)	1	\$ 76.30	\$ 76.30
31	RADIATOR HOSE (LOWER)	1	\$ 75.00	\$ 75.00
32	RADIATOR FAN MOTOR	1	\$ 389.80	\$ 389.80
33	RADIATOR FAN COWLING	1	\$ 160.60	\$ 160.60
34	RADIATOR FAN BLADE	1	\$ 99.70	\$ 99.70
35	FRONT TEMPERATURE SENSOR	1	\$ 179.60	\$ 179.60
36	ALTERNATOR	1	\$ 898.30	\$ 898.30
37	HORN	2	\$ 89.60	\$ 179.20
38	BATTERY TRAY	1	\$ 78.30	\$ 78.30
39	BATTERY BASE PANEL	1	\$ 129.60	\$ 129.60
40	FRONT FENDER	2	\$ 435.20	\$ 870.40
41	FRONT FENDER COWLING	2	\$ 125.30	\$ 250.60
42	TAIL GATE	1	\$ 849.90	\$ 849.90
43	TAIL GATE OUTER HANDLE	1	\$ 164.90	\$ 164.90
44	TAIL GATE LOGO	1	\$ 24.70	\$ 24.70
45	TAIL GATE EMBLEM "FIT"	1	\$ 28.80	\$ 28.80
46	TAIL GATE WINDSCREEN MOULDING	2	\$ 76.00	\$ 152.00
47	TAIL GATE DAMPER	2	\$ 194.40	\$ 388.80
48	TAIL GATE HINGE	2	\$ 42.00	\$ 84.00
49	TAIL GATE STOPPER	2	\$ 12.00	\$ 24.00
50	TAIL GATE INNER LOCK	1	\$ 169.40	\$ 169.40
51	TAIL GATE LOCK CATCH	1	\$ 25.00	\$ 25.00
52	TAIL GATE WEATHER STRIP	1	\$ 134.50	\$ 134.50
53	TAIL GATE INNER TRIM	1	\$ 372.20	\$ 372.20
54	REAR BUMPER	1	\$ 490.00	\$ 490.00
55	REAR BUMPER TOWING COVER	1	\$ 86.00	\$ 86.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SJK9171D
 MODEL : HONDA FIT
 DATE OF ACCIDENT : 24.06.2024
 TIME OF ACCIDENT : 07:40 HOURS

56	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 35.20	\$ 70.40	+
57	TAIL LAMP <i>cracked</i>	2	\$ 296.10	\$ 592.20	✓
58	TAIL LAMP PANEL (OUTER) <i>Repair</i>	2	\$ 168.30	\$ 336.60	+
59	TAIL LAMP INNER PANEL (LOWER) <i>Repair</i>	2	\$ 284.70	\$ 569.40	+
60	REAR FENDER <i>Repair</i>	2	\$ 677.80	\$ 1,355.60	+
61	REAR FENDER INNER COWLING <i>new</i>	2	\$ 78.10	\$ 156.20	+
62	REAR FENDER INNER TRIM <i>Delud</i>	2	\$ 298.90	\$ 597.80	✓
63	REAR FENDER INNER UPPER TRIM <i>new</i>	2	\$ 189.60	\$ 379.20	+
64	REAR WHEEL HOUSE PANEL <i>Repair</i>	2	\$ 997.70	\$ 1,995.40	+
65	REAR FENDER AIR VENT <i>new</i>	2	\$ 72.30	\$ 144.60	+
66	REAR QUATER GLASS C/W MOULDING <i>new</i>	2	\$ 280.00	\$ 560.00	+
67	REAR END PANEL <i>Distorted</i>	1	\$ 356.70	\$ 356.70	✓
68	REAR END PANEL TOP GARNISH <i>Delud</i>	1	\$ 116.20	\$ 116.20	✓
69	REAR FLOOR PANEL <i>Buckend</i>	1	\$ 1,147.70	\$ 1,147.70	✓ 955
70	REAR FLOOR PANEL TOP BOARD <i>Delud</i>	1	\$ 185.60	\$ 185.60	✓
71	REAR TOOLS BOX <i>Delud</i>	1	\$ 294.20	\$ 294.20	✓
72	REAR CHASSIS FRAME LH <i>Repair</i>	1	\$ 798.80	\$ 798.80	+
73	REAR CHASSIS TOP PANEL <i>Repair</i>	2	\$ 196.10	\$ 392.20	+
74	REAR EXHAUST BOX	1	\$ 896.30	\$ 896.30	+
75	REAR EXHAUST INSULATOR <i>MP</i>	1	\$ 58.40	\$ 58.40	+
76	REAR EXHAUST GASKET (SET)	1	\$ 60.00	\$ 60.00	+
77	REAR EXHAUST MOUNTING <i>MP</i>	4	\$ 21.20	\$ 84.80	+

10685.70
 8548.56

TOTAL PRICE \$ 24,623.60
 LESS 20% \$ 4,924.72
\$ 19,698.88

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>combed</i>	1	\$ 50.00	\$ 50.00	✓
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT BUMPER LOWER GRILLE CLIP (SET) <i>MP</i>	1	\$ 40.00	\$ 40.00	✓
4	FRONT WIPER PANEL GARNISH CLIP (SET) <i>MP new</i>	1	\$ 40.00	\$ 40.00	✓
5	ENGINE UNDER COVER CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	✓
6	CENTRE GRILLE CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	20
7	BONNET SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SJK9171D
 MODEL : HONDA FIT
 DATE OF ACCIDENT : 24.06.2024
 TIME OF ACCIDENT : 07:40 HOURS

8	FRONT AIR GUARD GARNISH CLIP (SET) <i>new</i>	1	\$	50.00	\$	50.00	+
9	FRONT SUPPORT PANEL SEALANT <i>new</i>	1	\$	60.00	\$	60.00	+
10	FRONT FENDER INNER GARNISH CLIP (SET) <i>new</i>	1	\$	40.00	\$	40.00	+
11	FRONT FENDER INNER SHIELD CLIP (SET) <i>new</i>	1	\$	40.00	\$	40.00	+
12	COOLANT <i>new</i>	1	\$	80.00	\$	80.00	40
13	REAR NUMBER PLATE <i>new</i>	1	\$	50.00	\$	50.00	-
14	REAR BUMPER CLIP (SET) <i>new</i>	1	\$	80.00	\$	80.00	30
15	TAIL GATE INNER TRIM CLIP (SET) <i>new</i>	1	\$	50.00	\$	50.00	30
16	TAIL GATE WINDSCREEN SEALANT <i>new</i>	1	\$	80.00	\$	80.00	40
17	TAIL GATE WINDSCREEN INNER SEAL <i>new</i>	1	\$	60.00	\$	60.00	30
18	TAIL LAMP CLIP (SET) <i>new</i>	2	\$	40.00	\$	80.00	+
19	TAIL LAMP PANEL (OUTER) SEALANT <i>new</i>	2	\$	60.00	\$	120.00	+
20	TAIL LAMP INNER PANEL (LOWER) SEALANT <i>new</i>	2	\$	60.00	\$	120.00	+
21	REAR FENDER SEALANT <i>new</i>	2	\$	80.00	\$	160.00	+
22	REAR FENDER INNER COWLING (SET) <i>new</i>	1	\$	50.00	\$	50.00	+
23	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$	50.00	\$	50.00	✓
24	REAR WHEEL HOUSE PANEL <i>new</i>	2	\$	80.00	\$	160.00	+
25	REAR QUATER GLASS SEALANT <i>new</i>	2	\$	60.00	\$	120.00	+
26	REAR QUATER GLASS INNER SEAL <i>new</i>	2	\$	40.00	\$	80.00	+
27	REAR QUATER GLASS SOLAR FILM <i>new</i>	2	\$	250.00	\$	500.00	+
28	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$	150.00	\$	150.00	60
29	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$	350.00	\$	350.00	+
30	REAR CHASSIS TOP PANEL SEALANT <i>new</i>	2	\$	150.00	\$	300.00	+
31	REVERSE CAMERA <i>new</i>	1	\$	450.00	\$	450.00	+
32	REVERSE SENSOR (4PCS) <i>new</i>	1	\$	380.00	\$	380.00	200

630 TOTAL \$ 4,050.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	600
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	600

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SJK9171D
 MODEL : HONDA FIT
 DATE OF ACCIDENT : 24.06.2024
 TIME OF ACCIDENT : 07:40 HOURS

3	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	X
4	TUFF COAT	\$ 450.00	40
5	REFOCUS HEADLAMP BEAM	\$ 60.00	X
6	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
7	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
8	REFOCUS HEADLAMP BEAM	\$ 60.00	X
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

1360

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	1200-
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	800
3	TUFF COAT	\$ 250.00	80
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SJK9171D
 MODEL : HONDA FIT
 DATE OF ACCIDENT : 24.06.2024
 TIME OF ACCIDENT : 07:40 HOURS

9	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
10	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
11	REMOVE AND REFIX REAR FENDER GLASS	\$ 180.00	X
12	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 100.00	X
13	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	X
14	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X

TOTAL

\$10,930.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 23,748.88
 TOTAL LABOUR COST : \$ 10,930.00
 TOTAL REPAIR COST : \$ 34,678.88

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Adrian Lim
 2/8 25/06/24
 15 Days.

total: 112988.56
 4/5 10HK

10HK.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: