



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

*medh'sg
Nanfar*

NO. : 48507

Customer :

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534
ATTN: CHINA TAIPING INSURANCE (S) PTE LTD

DATE : 10/12/2024
CLAIM NO. : 12677
POLICY NO. :

FROM : MIGNON

VEHICLE NO. : FBL6652S
MAKE/MODEL : YAM / MTM850A(XSR900)

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	Alignment front fork n Handlebar - (REPORTED BY MECHANIC) <i>101</i>	Repair	1.00	\$186.00	186.00 ✓
2	BEARING REAR WHEEL (6204) <i>PC</i> P/N: 38880 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	48.00
3	COVER ENGINE (GB RACING) SET <i>CVT</i> P/N: 80376 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,008.00	1,008.00
4	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	Supply/Install	6.00	\$85.00 <i>55</i>	510.00
5	MID BEARING (B6004Z) <i>(Rim bay) - RE</i> P/N: 22614 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
6	RIM REAR ASSY <i>(Rim bay) - RE</i> - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,138.00	1,138.00
7	RUBBERPE PEDAL GEAR - (REPORTED BY MECHANIC) <i>CVT</i>	REPLACE	1.00	\$124.00	124.00
8	SEAL OIL <i>PC</i> P/N: 65151 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
9	SHOCK ABSORBER REAR (OHLINS) <i>BT</i> - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3,410.00	3,410.00



bizSAFE₃



Blk 8 Defu South Street 1, #04-28, JTC Defu Industrial City, Singapore 533758 | Tel: +65 6281 6520 | www.bhh.com.sg
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) + 65 6284 2969, (Accounts) + 65 6281 6759

CERT NO.: 2002 1-0383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
10	SLIDER FORK FRONT P/N: 35324 (REPORTED BY MECHANIC)	REPLACE	1.00	\$217.00	217.00
11	SLIDER REAR AXLE (REPORTED BY MECHANIC)	REPLACE	1.00	\$217.00	217.00
12	STAND SIDE P/N: 53749 (REPORTED BY MECHANIC)	REPLACE	1.00	\$107.00	107.00
13	VALVE TYRE 11.3MM BLUE (RACING VALVE) P/N: 41896 (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00

SUB TOTAL	\$7,057.00
GST @ 9 %	\$635.13
GRAND TOTAL (SGD)	\$7,692.13

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



MIGNON

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Steve CLKKJ
11/12/24, 12 Mon
m K
P/P
Lg BL sm
2 dgs



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



DATA PROTECTION
ASSURED

bizSAFE₃



Blk 8 Defu South Street 1,
Fax: (Main) + 65 6281 2830

+65 6281 6520 | www.bhh.com.sg
+65 6281 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002 1 0383
ISO 9001:2015