


PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S



PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 16 of 16)

PHOTOGRAPHS FOR VEHICLE NO. : SNK 9249S

