

MY CAR CONSULTANT PTE LTD
(Co Reg. No. 201605878Z)
60 JALAN LAM HUAT
CARROS CENTRE #05-68
Singapore 737869
Tel: 93911482

TO	: ECICS	DATE	: 9-Dec-24
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
VEHICLE DETAILS			
		VEHICLE NO	: SNK9249S
		MODEL	: NISSAN SERENA

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	LIST	LIST
1	REAR BUMPER / BR	1	\$ 1,359.00	\$ 1,359.00
2	REAR BUMPER SIDE RETAINER bro	2	\$ 115.00	\$ 230.00
3	REAR BUMPER SIDE GARNISH / CRV (LH) 12	12	\$ 212.00	\$ 424.00
4	TAILGATE / DN	1	\$ 2,789.00	\$ 2,789.00
5	TAILGATE INNER TRIM BOARD X nn	1	\$ 512.00	\$ 512.00
6	TAILGATE OUTER CHROME GARNISH LOWER X nn	1	\$ 498.00	\$ 498.00
7	TAILGATE LOCK / Jammed	1	\$ 323.00	\$ 323.00
8	TAILGATE EMBLEM 'POWER' / MR	1	\$ 75.00	\$ 75.00
9	TAILGATE EMBLEM 'STAR' X nn	1	\$ 86.00	\$ 86.00
10	TAILGATE EMBLEM 'HIGHWAY' / n/c	1	\$ 62.00	\$ 62.00
11	TAILGATE WEATHERSTRIP / TN	1	\$ 258.00	\$ 258.00
12	TAILGATE WINDSCREEN GLASS CW SPOILER X nn	1	\$ 3,598.00	\$ 3,598.00
13	TAILGATE WINDSCREEN MOULDING X nn	1	\$ 211.00	\$ 211.00
14	TAILAMP LH X nn	1	\$ 1,125.00	\$ 1,125.00
15	REAR END PANEL / DN	1	\$ 814.00	\$ 814.00
16	REAR END PANEL TOP GARNISH - BR	1	\$ 312.00	\$ 312.00
17	REAR FLOOR PANEL X nn	1	\$ 1,025.00	\$ 1,025.00
18	REAR FLOOR TOP BOARD / BR	1	\$ 312.00	\$ 312.00
19	REAR FENDER INNER TRIM BOARD (LH) - BR	21	\$ 715.00	\$ 1,430.00

TOTAL PRICE \$ 20,272.00
LESS 10% \$ 2,027.20

6542
-10%
5887.80

SUB TOTAL PRICE \$ 18,244.80

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP SET / M	1	\$ 50.00	\$ 50.00 30
2	REAR WINDSCREEN GLASS SEALANT X nn	1	\$ 100.00	\$ 100.00
3	REAR WINDSCREEN GLASS INNER SEAL X nn	1	\$ 80.00	\$ 80.00
4	REAR NUMBER PLATE X nn	1	\$ 100.00	\$ 100.00
5	REVERSE SENSOR / shd	1	\$ 250.00	\$ 250.00 200

TOTAL \$ 580.00 230

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	SUPPORT PANEL. RESTRUCTURE REAR CRASH MANAGEMENT	\$ 1,400.00	1000	
2	SPRAY PAINTING TO AFFECTED AREA.	\$ 1,200.00	800	
3	REMOVE AND REFIT TAILGATE MECHANISM	\$ 200.00	50	
4	REMOVE AND REFIT UPHOLSTERY, SEAT ETC	\$ 400.00	80	
5	REMOVE AND REFIT REAR REVERSE SENSOR	\$ 150.00	30	
6	REMOVE AND REFIT REAR WINDSCREEN GLASS	\$ 150.00	X	
7	TO APPLY TUFF COAT.	\$ 200.00	20	
8	SRS RESET	\$ 350.00	X	

TOTAL \$ 4,050.00 1980

ESTIMATE REPORT

TOTAL PARTS COST : \$ 18,824.80
TOTAL LABOUR COST : \$ 4,050.00
TOTAL REPAIR COST : \$ 22,874.80

8097.80

L/S - 6478.24
= 6500

Steve (LKK)
9/12/24, 4.30pm
n n
L/S
AL sy
7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: