

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : DHOM130007972300 Date: 13<sup>th</sup> Dec 2024

Our Ref : CS/UOI24120132/Tqh3e2

## M/s United Overseas Insurance Ltd

146 Robinson Road #02-01 UOI Building Singapore 068909 (The Motor Claims Department)

Dear Sirs/Madam,

## AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO. SKR 366U ACCIDENT ON 07/12/2024

Instruction was received to inspect the vehicle Reg. No. SKR 366U. The inspection was conducted on 10/12/2024 at the premises of M/s Sng Ah Tee Motor & Panel Service Pte Ltd, Blk 3, Pioneer Road North, #01-18, Singapore 628457.

The following vehicle information was recorded:

Registration Number : SKR 366U

Make/Model : Mercedes Benz A180 (R17)

Year of Registration : 2015 Body Colour : Red

Chassis Number : WDD1760422J325429

Engine Capacity : 1595 cc

The vehicle sustained damages at the front portion. (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as "**Total Loss**".

Market Value S\$ 10,000.00 (est)

Less: LTA Reimbursement Value (RV) (S\$ 7,148.00)

Nett Liability S\$ 2,852.00

Vehicle Inspected By:

MOHAMAD TAUFIKH M.MATAI. AMSAE-A

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.