



ABSOLUTE APPRAISAL SERVICES PTE LTD

Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722

Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle Inspection Report

To: Ang Nguang Seng
C/o: 160 Sin Ming Drive, #02-09
Sin Ming AutoCity (S) 575722

Date of report: 28.04.2024
Date of request: 09.04.2024
Date of inspection: 09.04.2024
Date of accident: 02.04.2024
Claim type: Third Party Claim

Report No: AAS/2024/079

Particulars of affected vehicle:

Registration no: SMH1691C
Make/Model: Volkswagen Touran 1.4 (A)
Year of registration: 2010/11
Colour: Metallic Brown

Odometer: 280154 km
Engine Capacity: 1390 cc
Engine no: CAV245542
Chassis no: WVGZZZ1TZBW043224

Condition of tires:

Front Left: 5mm
Make: Pirelli
Rear Left: 5mm
Make: Pirelli

Front Right: 5mm
Make: Pirelli
Rear Right: 5mm
Make: Pirelli

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

The Assignment

The inspection was conduct at M/s. 833 Motorsports Pte Ltd
160 Sin Ming Drive, #02-09
Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

Assessment

Repairer's estimate:	\$ 10,434.07
Revised estimate:	\$ 7,449.42
Recommended reserve:	\$ 5,950.00 (Lump sum)

Estimated normal duration of repairs : 5 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD

Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722

Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle No: SMH1691C

Report No: AAS/2024/079

W/O PREJUDICE

Point of impact

At the RHS rear portion.

General description of damages

The RHR door, RHR quarter panel, RHR road wheel, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s 833 Motorsports Pte Ltd as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$7,449.42

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$5,950.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 6 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 40 photographs.

Your Faithfully

Absolute Appraisal Services Pte Ltd



Nicky Seah

Automobile Appraiser

MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD

Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722

Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle No: SMH1691C

Report No: AAS/2024/079

Appraisement Schedule

S/N	Parts Description	Qty	Condition	Repairer's Est	Revised Est
1	RHR door	1	Dented	\$ 2,444.04	\$ 2,444.04
2	RHR door outer handle	1	Grazed	\$ 233.15	\$ 233.15
3	RHR door protector	1	Grazed	\$ 140.71	\$ 140.71
4	RHR door weather seal	1	Necessary	\$ 280.12	\$ 280.12
5	RHR door sound absorber	1	Necessary	\$ 43.65	\$ 43.65
6	RHR door lock	1	Distorted	\$ 388.53	\$ 388.53
7	RHR door glass regulator	1	Serviceable	\$ 553.67	-
8	RHR door glass regulator motor	1	Serviceable	\$ 650.15	-
9	RHR quarter panel	1	Dented	\$ 1,780.27	\$ 1,780.27
10	RHR quarter glass w moulding	1	Not Necessary	\$ 534.68	-
Total:				\$ 7,048.97	\$ 5,310.47
-10%				\$ 704.90	\$ 531.05
List total:				\$ 6,344.07	\$ 4,779.42
1	RHR quarter glass sealant	1	Not Necessary	\$ 60.00	-
2	RHR sport rim	1	Grazed/Chipped	\$ 850.00	\$ 600.00
Special nett total:				\$ 910.00	\$ 600.00
Parts Total:				\$ 7,254.07	\$ 5,379.42



ABSOLUTE APPRAISAL SERVICES PTE LTD

Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722

Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle No: SMH1691C		Report No: AAS/2024/079	
S/N	Labour Description	Repairer's Est	Revised Est
1	Renew RHR sport rim.	\$ 50.00	\$ 20.00
2	Conduct wheel alignment.	\$ 100.00	\$ 60.00
3	Remove & transfer RHR door fittings.	\$ 150.00	\$ 100.00
4	Renew RHR quarter glass.	\$ 180.00	-
5	Remove & refit fuel tank to make way for replacement.	\$ 150.00	-
6	Remove & refit rear luggage trim, rear seats, etc to make way for replacement/repairs.	\$ 200.00	\$ 100.00
7	Anti rust on affected panels.	\$ 100.00	\$ 40.00
8	To renew damaged parts, conduct straightening & panel beating on affected area. Re-align affected area.	\$ 1,250.00	\$ 750.00
9	Spray painting on replaced & affected parts/areas.	\$ 1,000.00	\$ 1,000.00
Labour Total:		\$ 3,180.00	\$ 2,070.00
Grand Total:		\$ 10,434.07	\$ 7,449.42

The final adjusted lump sum amount is \$5,950.00

Under normal circumstances, the repair should be completed within a reasonable period of 6 working days.

40 Photographs were taken at the time of inspection.



















