



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24120135/Knh3e2
16 RAFFLES QUAY	Date:	12/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8936L	Veh. Inspected	SHB 7822T
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24010636MFCT	Excess	\$0.00
Assign From	EILEEN WANG	Assign Date	10/12/2024

2. Vehicle Details

Make & Model	TOYOTA PRIUS (A)	C.C	1798
Engine No.	2ZR2C52930	Year of Reg.	30/08/2019
Chassis No.	JTDKB3FU103083452	Colour	METALLIC PEARL WHITE / RED
Odometer	380202 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	GOODRIDE	8
L/H Front Tyre	195/65R15	GOODRIDE	8
R/H Rear Tyre	195/65R15	GOODRIDE	7
L/H Rear Tyre	195/65R15	GOODRIDE	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/12/2024	Inspection Date	10/12/2024
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days