

Not Authorized
21 Sep @ 3150h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2412-014

SHB7822T

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

10 DEC 2024

SHB7822T

JTDKB3FU103083452

200303878K

TOYOTA

PRIUS

3/12/2024

SHC8936L/FCI

30/8/2019

PART

- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 SUPPORT, RADIATOR, UPPER LH
- 1 HOOD SUB-ASSY
- 1 HINGE ASSY, HOOD, LH
- 1 HINGE ASSY, HOOD, RH
- 1 LAMP ASSY, FOG, LH
- 1 UNIT ASSY, HEADLAMP, LH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 EMBLEM, SIDE PANEL LH
- 1 LINER, FRONT FENDER, LH

LIST

\$	CM	653.31	—
\$	Sm	100.17	X
\$	n	902.16	X
\$	n	59.85	X
\$	dis	74.97	—
\$	Sm	99.33	X
\$	n	1,243.20	X
\$	n	74.34	X
\$	n	74.34	X
\$	Sm	1,200.78	X
\$	CM	3,325.56	—
\$	n	1,236.69	X
\$	n	68.88	—
\$	Sm	255.36	X

TOTAL	\$	9,368.94
25%	\$	2,342.24
	\$	7,026.71

Special Nett

- 1 FRT BUMPER CLIP
- 1 FENDER LINER CLIP
- 1 FRT LH BUMPER RETAINER CLIP
- TOTAL**

\$	n	65.00	65.00
\$	n	130.00	X
\$	n	65.00	X
\$		260.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7822T**AAD2412-014****TOTAL PARTS \$ 7,286.71****LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 *3001*

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 *4401*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 240.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 *2001***TOTAL \$ 3,590.00****Over All Total \$ 10,876.71****(PART-BY-PART) Repair Days**~~06 days~~*2 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: