

ASS. REC. BY:

REF:

09/10/24 20135/Kuh3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HB 78227

Yr Regn:

08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C

1798

Colour Mr. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

380202

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTD KB 3FU103083452

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Goodride

Front

Rear

R/Bal.

8

mm

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

3/12/24

D.O.A.

10/12/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/12 11:00 am 3150h. Car in Ured 8 7726.71, 7120

Date/Time, File Pass to?

☐

: Prel. Report

1) 11/12 11:00 am

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

: Fuel

: Others

TOTAL

Report Format :

TP

Lump Sum / I.B.A. (\$

3150

Not Authored
21 Sep @ 3150h

Trans-cab Auto Services Pte Ltd

AAD2412-014

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7822T

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

10 DEC 2024

SHB7822T

JTDKB3FU103083452

200303878K

TOYOTA

PRIUS

3/12/2024

SHC8936L/FCI

30/8/2019

PART

- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 SUPPORT, RADIATOR, UPPER LH
- 1 HOOD SUB-ASSY
- 1 HINGE ASSY, HOOD, LH
- 1 HINGE ASSY, HOOD, RH
- 1 LAMP ASSY, FOG, LH
- 1 UNIT ASSY, HEADLAMP, LH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 EMBLEM, SIDE PANEL LH
- 1 LINER, FRONT FENDER, LH

LIST

\$	CM	653.31	—
\$	Sm	100.17	X
\$	n	902.16	X
\$	n	59.85	X
\$	Dir	74.97	✓
\$	Sm	99.33	X
\$	n	1,243.20	X
\$	n	74.34	X
\$	n	74.34	X
\$	Sm	1,200.78	X
\$	CM	3,325.56	—
\$	n	1,236.69	X
\$	n	68.88	✓
\$	Sm	255.36	X

TOTAL	\$	9,368.94
25%	\$	2,342.24
	\$	7,026.71

Special Nett

- 1 FRT BUMPER CLIP
- 1 FENDER LINER CLIP
- 1 FRT LH BUMPER RETAINER CLIP
- TOTAL**

\$	n	65.00	60.00
\$	n	130.00	X
\$	n	65.00	X
\$		260.00	

Trans-cab Auto Services Pte Ltd**AAD2412-014**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7822T

TOTAL PARTS	\$	7,286.71
--------------------	-----------	-----------------

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 *3001*

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 *4401*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 240.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 *2001*

TOTAL	\$	3,590.00
--------------	-----------	-----------------

Over All Total	\$	10,876.71
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days~~06~~ days*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHB7822T
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2C52930
Chassis No.:	JTDKB3FU103083452
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	30 Aug 2019
First Registration Date:	30 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2027
PARF Rebate Amount:	\$9,972.00

Intended COE Rebate Details

COE Expiry Date:	29 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,463.00
COE Rebate Amount:	\$8,010.00
Total Rebate Amount:	\$17,982.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Dec 2024

OK