

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047

Tel : 64810304 Fax : 64815587

Reg No : 200600989K

GST No : 200600989k

Longpac

Estimate Repair

Motorcar Claim Department

Attn Officer In Charge

Date : 10/12/2024

Accident Involving SMG6462U & YP7369K ON 8 DEC 2021

SMG6462U

HONDA HRV

Not Withheld
Minor B&P
\$4444.68

Item	Descriptions	Amount
1	Tail Gate	\$ 1,093.50 ✓
2	Tail Gate Lock	\$ 178.20 X
3	Third Brake Light	\$ 248.00 X
4	Tail Gate Center Chrome Garnish	\$ 274.20 ✓
5	Tail Gate Windscreen Moulding RH & LH @\$24.80 X 2	\$ 49.60 ✓
6	RL Tail Lamp	\$ 438.50 ✓
7	RL Tail Gate Reflector	\$ 294.60 ✓
8	RL Bumper Corner	\$ 107.30 ✓
9	Rear Bumper	\$ 583.30 ✓
10	RL Bumper Reflector	\$ 185.20 ✓
11	RL Bumper Retainer	\$ 19.80 ✓
12	Rear End Panel	\$ 498.60 X
13	RL Wheel Arch	\$ 191.60 ✓
14	Rear Center Lock Buzzer	\$ 82.50 X
208		
Total For Parts		\$ 4,244.90

S/N Item (s)

1	Rear Bumper Clips	\$ 35.00 ✓
2	HRV Emblem	\$ 24.80 ✓
3	HONDA Logo	\$ 24.80 ✓
4	Rear Windscreen Sealant	\$ 40.00 ✓
5	Rear Parking Sensor - 1 Set 4 Pcs	\$ 387.90 ✓

Total For S/N \$ 512.50

Labour & Misc

1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel	\$ 1,600.00 700d 700d
2	Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ 700.00 650d
3	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ 150.00 120d
4	Remove & Refix Rear Windscreen To Facilitate Repair	\$ 80.00 30d
5	Check Wiring, Lighting System & Center Locking For Proper Function	\$ 120.00 30d
5	Cavity Preservation On All Affected Areas	

\$ 2,650.00

Total For Parts & Labour \$ 7,407.40

No Of Days For Repair 6 Days ?

5 days

Ready Auto Care Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: