



ASSESSMENT FOR REPAIR : FBB6934G
YAMAHA X-1R
COE EXPIRY : 2027.03.31

not Authorized
 per 90096608
 1/7/24
 2/55
 telephone after 12pm
 3 days

Lump Sum

Part by Part

Qty	Description
1	HANDLE BAR
1	RH - BRAKE PUMP (BREMBO) with level
1	RH - MIRROR
1	BAR END
1	RH - FRONT SIGNAL LIGHT
1	BRAKE PEDAL
1	RH - RIDER FOOTREST
1	RH - ENGINE COVER / CLUTCH COVER
1	RH - PILLION FOOTPEG
1	SPEEDOMETER FRONT COVER

Repairer's Estimate	1st Survey	Repair Survey	Final Survey
299.75	?		
970.10	CU7 ✓		
55.00	mis ✓		
72.00	CU7 ✓		
65.00	CU7 ✓		
55.00	CU7/3rd ✓		
55.00	CU7 ✓		
272.50	rx		
28.00	CU7 ✓		
85.00	CU7 ✓		

1,957.35

Special Nett Items

STEERING CONE & BEARING
 FRONT FORK ALIGNMENT
 WHEEL ALIGNMENT
 FRAME ALIGNMENT
 PLASTIC COVER SET
 FULL SET COVER SET
 YOSHIMURA TRIOVAL

130.00	17X		
230.00	11X		
130.00	17X		
210.00	17X		
348.80	600 X		
763.00	CU7 ✓		
1,853.00	CU7 ✓		

3,664.80

Total Parts

5,622.15

Labour Charges

1 Workmanship to renew damage parts & areas
 \$100 per days X 4 days

400.00 250
 400.00

Total Parts & Labours Concluded

6,022.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SANFU MOTOR PTE LTD acknowledged by Repairer

Company Reg No.: 200612487G

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com