



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBB 6934G

| REPLACEMENT OF PARTS | | | | |
|----------------------|--|----------------------|------------------------|-------------------|
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1 | HANDLE BAR | * CHECK | \$299.75 | \$0.00 |
| 1 | RH - BRAKE PUMP (BREMBO) WITH LEVEL | CUT | \$970.10 | \$970.10 |
| 1 | RH - MIRROR | MISSING | \$55.00 | \$55.00 |
| 1 | BAR END | CUT | \$72.00 | \$72.00 |
| 1 | RH - FRONT SIGNAL LIGHT | CRACKED | \$65.00 | \$65.00 |
| 1 | BRAKE PEDAL | CUT/BENT | \$55.00 | \$55.00 |
| 1 | RH - RIDER FOOTREST | CUT | \$55.00 | \$55.00 |
| 1 | RH - ENGINE COVER / CLUTCH COVER | TO REPAIR SEE LABOUR | \$272.50 | \$0.00 |
| 1 | RH - PILLION FOOTPEG | CUT | \$28.00 | \$28.00 |
| 1 | SPEEDOMETER FRONT COVER | CUT | \$85.00 | \$85.00 |
| | LESS 0.00 / 10.00% DISCOUNT | | \$0.00 | (\$138.51) |
| | | | \$1,957.35 | \$1,246.59 |
| Special Nett | | | | |
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1 | STEERING CONE & BEARING (SN) | NOT NECESSARY | \$130.00 | \$0.00 |
| 1 | SET FULL SET COVER (SN) } | CUT | \$763.00 | \$763.00 |
| 1 | SET PLASTIC COVER (SN) } | CUT | \$348.80 | \$0.00 |
| 1 | YOSHIMURA TRIOVAL (SN) | CUT | \$1,853.00 | \$1,300.00 |
| | | | \$3,094.80 | \$2,063.00 |
| Labour | | | | |
| | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| | FRONT FORK ALIGNMENT | NOT NECESSARY | \$230.00 | \$0.00 |
| | WHEEL ALIGNMENT | NOT NECESSARY | \$130.00 | \$0.00 |
| | FRAME ALIGNMENT | NOT NECESSARY | \$210.00 | \$0.00 |
| | WORKMANSHIP TO RENEW DAMAGE PARTS & AREAS \$100 PER DAYS X 4 DAYS. INCLUSIVE OF THE REPAIR OF RH - ENGINE COVER / CLUTCH COVER | | \$400.00 | \$250.00 |
| | | | \$970.00 | \$250.00 |
| GRAND TOTAL | | | \$6,022.15 | \$3,559.59 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

| | | | |
|---|--|--|-------------------|
| | RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$269.78 NETT) | | \$3,559.59 |
| Report Ref No: CS/LIP24070011/Unh3 | | | |

MARKET VALUE: \$5,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$1,718.00=NETT VALUE: \$3,282.00

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.