



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24070011/Unh3
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	20/08/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJV 8812L	Veh. Inspected	FBB 6934G
Policy No.	-	Coverage	0
Claim No.	IVS24/1257	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	01/07/2024

2. Vehicle Details

Make & Model	YAMAHA X-1R	C.C	135
Engine No.	4S3502221	Year of Reg.	22/06/2007
Chassis No.	4S3502221	Colour	BLUE
Odometer	80000 KM	Steering	DAMAGED
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	70-90-17	MAXXIS	6
L/H Front Tyre			
R/H Rear Tyre	70-90-17	MAXXIS	6
L/H Rear Tyre			

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/06/2024	Inspection Date	01/07/2024
Survey held at	SANFU MOTOR PL 1 KAKI BUKIT AVENUE 6 #02-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days