

ONE GARAGE PTE LTD

8 KAKI BUKIT AVENUE 4 #03-33 PREMIER@KAKI BUKIT

SINGAPORE 415875

TEL: 96311088

Auto and General

TO	: GREAT AMERICAN	DATE	: 16/12/2024
VEHICLE NO	: SNR5296U (2016)		<i>Xiao Chan</i>
VEHICLE MODEL	: AUDI Q5		
CHASSIS NO	: WAUZZZ8R9HA019475		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>torn</i>	1	\$ 3,254.00	\$ 3,254.00
2	FRONT BUMPER SIDE HOLDER <i>new</i>	1	\$ 101.00	\$ 101.00
3	HEADLAMP <i>cracked</i>	1	\$ 3,418.00	\$ 3,418.00
4	HEADLAMP LOWER BRACKET <i>3 cracked</i>	1	\$ 147.00	\$ 147.00
5	HEADLAMP LOWER MOUNTING	1	\$ 98.00	\$ 98.00
6	FRONT FENDER <i>dented</i>	1	\$ 1,190.00	\$ 1,190.00
7	FRONT FENDER INNER SHIELD (FRONT) <i>new</i>	1	\$ 303.00	\$ 303.00
8	FRONT FENDER INNER SHIELD (REAR) <i>new</i>	1	\$ 315.00	\$ 315.00
9	BONNET <i>new</i>	1	\$ 4,651.00	\$ 4,651.00
10	FRONT WHEEL RIM <i>new</i>	1	\$ 1,652.00	\$ 1,652.00
11	FRONT SHOCK ABSORBER <i>new</i>	1	\$ 1,483.00	\$ 1,483.00
12	FRONT SHOCK ABSORBER FORK ARM <i>new</i>	1	\$ 366.00	\$ 366.00
13	FRONT KNUCKLE ARM <i>new</i>	1	\$ 1,136.00	\$ 1,136.00
14	FRONT WHEEL HUB <i>3 damaged</i>	1	\$ 479.00	\$ 479.00
15	FRONT WHEEL HUB BEARING	1	\$ 246.00	\$ 246.00
16	FRONT UPPER ARM <i>new</i>	1	\$ 561.00	\$ 561.00
17	FRONT LOWER ARM <i>Bent</i>	1	\$ 539.00	\$ 539.00
18	FRONT CONTROL ARM <i>Bent</i>	1	\$ 458.00	\$ 458.00
19	FRONT ANTI ROLL BAR LINKAGE <i>3 new</i>	1	\$ 192.00	\$ 192.00
20	STEERING RACK & PINION <i>new</i>	1	\$ 6,782.00	\$ 6,782.00

TOTAL PRICE: \$ 27,371.00

LESS 5% \$ 1,368.55

SUB TOTAL PRICE: \$ 26,002.45

*10132
962540
S.N. 800*

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	FRONT FENDER INNER SHIELD CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
3	FRONT TYRE <i>new</i>	1	\$ 380.00	\$ 380.00

TOTAL : \$ 460.00

80

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 800.00	500	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 800.00	600	
3	WIRING CHECK	\$ 50.00	30	
4	TO SPRAY TUFF COAT	\$ 100.00	30	
5	TO REMOVE FRONT UNDERCARRIAGE	\$ 380.00	200	
6	TO REMOVE STEERING RACK & PINION	\$ 180.00	X	
7	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80	
8	TO PERFORM DIAGNOSTIC TEST	\$ 200.00	150	

TOTAL: \$ 2,660.00

1590

ESTIMATE REPORT

TOTAL PARTS COST: \$ 26,462.45

TOTAL LABOUR COST: \$ 2,660.00

TOTAL REPAIR COST: \$ 29,122.45

Total: 12095.40

2/s: 9.6K. ✓

06 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: