

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883

TEL: 6842 9089 FAX: 6841 2869

REG NO : 48992400W

Vehicle Number: GBG5062C

Vehicle Model : Toyota Hiace Van Turbo 5DR MT

Manufacturing Year : 2017

Chassis : JTFHT02P300231843

S/N.	Item Description	Amount (\$)
1	Rear Boot / <i>ON</i>	\$ 1,377.00
2	Rear Boot Toyota Logo / <i>NC</i>	\$ 76.10
3	Rear Boot Absorber x 2 pcs X	\$ 952.14
4	Rear Boot Lock / <i>Journal</i>	\$ 393.63
5	Rear Boot Lock Protector X	\$ 89.70
6	Rear Boot Catch X	\$ 127.40
7	Rear Boot Stopper x 2 pcs X	\$ 219.65
8	Rear Boot Stopper Cushion x 2 pcs X	\$ 97.61
9	Rear Number Plate Top Garnish X	\$ 302.68
10	Rear Number Plate Lamp x 2 pcs X	\$ 325.58
11	Rear Boot Weatherstrip / <i>CR9</i>	\$ 564.28
12	Rear Boot Inner Trimboard Clip x 1 set X	\$ 50.00
13	Rear Bumper / <i>ON</i>	\$ 910.80
14	Rear Bumper Side Retainer x 2 pcs / <i>RR</i>	\$ 81.40
15	Rear Bumper Center Bracket x 4 pcs / <i>BT</i>	\$ 158.40
16	Rear Bumper Clip x 1 set / <i>NC</i>	\$ 50.00
17	Rear Corner Garnish x 2 pcs X	\$ 189.40
18	End Panel (Inner) X <i>R</i>	\$ 804.10
19	End Panel (Outer) / <i>ON</i>	\$ 270.20
20	End Panel Top Scuff Plate X	\$ 219.40
Total :		\$ 7,259.47
Less 25% :		\$ 1,814.87
Amount :		\$ 5,444.60

30

S/N	Special Nett Item	Amount (\$)
1	Reverse Sensor x 2 pcs / <i>SMH1</i>	\$ 280.00
2	"TOYOTA" Sticker / <i>NC</i>	\$ 30.00
3	"Hiace" Sticker / <i>NC</i>	\$ 30.00
4	70KM/H Sticker / <i>NC</i>	\$ 30.00

5	Rear Windscreen Sealant / <i>APC</i>	\$	80.00	<i>40</i>
6	End Panel Sealant / <i>APC</i>	\$	80.00	<i>30</i>
7	Rear Number Plate X	\$	30.00	
8	Rear View Camera X	\$	350.00	
	Amount :	\$	910.00	

Labour	Amount (\$)	
To check rear wiring system	\$ 80.00	<i>30</i>
To remove & install reverse sensors	\$ 120.00	<i>30</i>
To remove & install rear interior garnishes, and trims to facilitate	\$ 280.00	<i>X</i>
To remove & reinstall rear windscreen	\$ 150.00	<i>120</i>
To transfer rear boot components from old boot to new boot	\$ 150.00	<i>50</i>
To apply anti-rusting coating on panels	\$ 280.00	<i>30</i>
Labour to remove, cut, change & panel beating	\$ 1,800.00	<i>800</i>
To putty and respray affected areas	\$ 1,500.00	<i>600</i>
Labour Total :	\$ 4,360.00	
Total (Parts & Labour)	\$ 10,714.60	

Steve CLKK
10/12/24, 11.00CL
W IL
C/S
by AL by
5 days

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: