



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24120141/Enh3m4
75 BRAS BASAH ROAD	Date:	23/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 9692H	Veh. Inspected	GBG 5062C
Policy No.	-	Coverage	0
Claim No.	MT/1307608-002	Excess	\$0.00
Assign From	MARCUS XIAO	Assign Date	10/12/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE	C.C	2982
Engine No.	1KD2745176	Year of Reg.	22/08/2017
Chassis No.	JTFHT02P300231843	Colour	SILVER
Odometer	375877 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15C	BRIDGESTONE	4
L/H Front Tyre	195R15C	BRIDGESTONE	4
R/H Rear Tyre	195R15C	BRIDGESTONE	4
L/H Rear Tyre	195R15C	BRIDGESTONE	4

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/12/2024	Inspection Date	11/12/2024 (10:58)
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days