

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 1752Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	1,286.00	1,286.00
1	FRONT BUMPER SIDE HOLDER	NOT NECESSARY	96.00	-
1	FRONT BUMPER SPONGE	CRACKED	194.00	194.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	745.00	-
1	FRONT BUMPER LOGO	NECESSARY	76.00	76.00
1	FRONT BUMPER FOG LAMP	CRACKED	322.00	322.00
1	FRONT BUMPER FOG LAMP COVER	CUT	148.00	148.00
1	HEADLAMP	CRACKED	2,836.00	2,836.00
1	HEADLAMP LOWER BRACKET	NOT NECESSARY	213.00	-
1	FRONT FENDER	NOT NECESSARY	641.00	-
1	FRONT FENDER INNER SHIELD	TORN	218.00	218.00
	LESS 5% DISCOUNT		-338.75	-254.00
			6,436.25	4,826.00
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT WHEEL RIM (SN)	NOT NECESSARY	1,300.00	-
1	FRONT BUMPER STICKER WRAP (SN)	NECESSARY	400.00	350.00
			1,780.00	430.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVE AND REFIT PARTS.		800.00	300.00
	SPRAY PAINTING TO AFFECTED AREA.		800.00	200.00
	WIRING CHECK.		50.00	30.00
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	TO PERFORM DIAGNOSTIC TEST.		200.00	120.00
			2,000.00	650.00
	GRAND TOTAL		10,216.25	5,906.00

Report Ref No. CS/INC24120142/Anh3m4(N)



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,700.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. CS/INC24120142/Anh3m4(N)

TOTAL FOR SPARE PARTS: \$ 8,216.25 \$ 5,256.00 TOTAL FOR LABOUR: \$ 2,000.00 \$ 650.00 TOTAL REPAIR COST: \$10,216.25 \$ 5,906.00

X; Z.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.