

ADVANCE AUTO GARAGE

TO :	INCOME	DATE :	17/12/2024
VEHICLE NO :	SLV1752Z (2017)	<i>Hui Kong</i>	
VEHICLE MODEL :	BMW 116D		
CHASSIS NO :	WBA1V72020V945303		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>Defend.</i>	1	\$ 1,186.00	\$ 1,186.00
2	FRONT BUMPER SIDE HOLDER <i>new</i>	1	\$ 96.00	\$ 96.00
3	FRONT BUMPER SPONGE <i>cracked</i>	1	\$ 194.00	\$ 194.00
4	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 745.00	\$ 745.00
5	FRONT BUMPER LOGO <i>new</i>	1	\$ 76.00	\$ 76.00
6	FRONT BUMPER FOG LAMP <i>cracked</i>	1	\$ 322.00	\$ 322.00
7	FRONT BUMPER FOG LAMP COVER <i>lt</i>	1	\$ 148.00	\$ 148.00
8	HEADLAMP <i>cracked</i>	1	\$ 2,836.00	\$ 2,836.00
9	HEADLAMP LOWER BRACKET <i>new</i>	1	\$ 213.00	\$ 213.00
10	FRONT FENDER <i>new</i>	1	\$ 641.00	\$ 641.00
11	FRONT FENDER INNER SHIELD <i>for</i>	1	\$ 218.00	\$ 218.00

TOTAL PRICE: \$ 6,425.00
 LESS 5% \$ 321.25
 SUB TOTAL PRICE: \$ 6,103.75

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS (SET) <i>2 per</i>	1	\$ 50.00	\$ 50.00
2	FRONT FENDER INNER SHIELD CLIPS (SET)	1	\$ 30.00	\$ 30.00
3	FRONT WHEEL RIM <i>new</i>	1	\$ 1,300.00	\$ 1,300.00

TOTAL : \$ 1,380.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 800.00	<i>300</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 800.00	<i>200</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	<i>X</i>	

TOTAL \$ 1,800.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 7,483.75
 TOTAL LABOUR COST: \$ 1,800.00
 TOTAL REPAIR COST: \$ 9,283.75

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Date:

total: 59067

4/3 4.71C

04 Days

4,700
4 days