

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01HONG LEONG BUILDING
SINGAPORE 048581

TEL: 63591800 FAX: 62320541
ATTN: Motor Claim Department

Estimate No: EST2400490
Date: 09 Dec 2024

Veh Reg No: SLC5387T
Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD 5DR

Chasis No: RU11114175

Claim Type: Third Party

Reg. Date: 18/05/2016

Accident Date: 06/12/2024

Your Ref No: SH8440T

TP Veh Reg No: SH8440T

Estimate Repair Cost to Vehicle No :SLC5387T

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price			
1	1 PC FRT DOOR LH	995.80	
2	1 PC FRT LH DOOR OUTER MOULDING	68.40	
3	2 PCS FRT DOOR HINGE LH	144.80	
4	1 PC FRT DOOR LH FRAME BLACK TAPE	58.30	
5	1 PC FRT DOOR RUBBER LH	168.50	
6	1 PC FRT DOOR LH GLASS REGULATOR ASSEMBLY	595.50	
7	1 PC FRT DOOR LOWER INNER PROTECTOR LH	166.20	
8	1 PC FRT LH WHEEL ARCH FENDER GARNISH	188.40	
9	1 PC FRT LH ROCKER PANEL SIDE SKIRT	464.90	
10	1 PC REAR DOOR LH	970.60	
11	2 PCS REAR DOOR HINGE LH	144.80	
12	1 PC REAR DOOR OUTER MOULDING LH	56.20	
13	1 PC REAR DOOR FRAME BLACK TAPE LH	58.30	
14	1 PC REAR DOOR GLASS REGULATOR ASSY LH	595.50	
15	1 PC REAR DOOR RUBBER LH	148.50	
16	1 PC REAR DOOR LOWER INNER PROTECTOR LH	146.30	
17	1 PC REAR LH FENDER ARCH GARNISH	189.20	
		5,160.20	
	Less 20%	1,032.04	4,128.16
Special Net			
18	1 SET FRT LH WHEEL ARCH FENDER GARNISH CLIPS	40.00	
19	1 SET FRT LH ROCKER PANEL SIDE SKIRTCLIPS	40.00	
20	1 SET REAR LH FENDER ARCH GARNISH CLIP	40.00	
		120.00	120.00
Labour			
21	1 TO CHECK WIRING	50.00	
22	1 TO REMOVE AND REFIX FRT DOOR GLASS	100.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01HONG LEONG BUILDING
SINGAPORE 048581

TEL: 63591800 FAX: 62320541
ATTN: Motor Claim Department

Estimate No: EST2400490
Date: 09 Dec 2024

Veh Reg No: SLC5387T
Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD 5DR

Chasis No: RU11114175

Claim Type: Third Party

Reg. Date: 18/05/2016

Accident Date: 06/12/2024

Your Ref No: SH8440T

TP Veh Reg No: SH8440T

Estimate Repair Cost to Vehicle No :SLC5387T

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
23	1	TO REMOVE AND REFIX REAR DOOR GLASS	100.00
24	1	TO REMOVE AND REFIT DOOR INNER TRIM	120.00
25	1	TO SPRAY UNDERSEAL	100.00
26	1	TO SPRAY PAINTING	1,200.00
27	1	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00
		2.870.00	2.870.00
		Total	S\$ 7,118.16
		Add GST @ 9%	640.63
		Total Amount Payable	<u>S\$ 7,758.79</u>

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED FIFTY EIGHT AND CENTS SEVENTY NINE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE