

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

Xiao Chun

M/S : MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 63591800 FAX: 62320541
ATTN: Motor Claim Department

Estimate No: EST2400490
Date: 09 Dec 2024

Veh Reg No: SLC5387T
Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD 5DR

Chasis No: RU11114175
Reg. Date: 18/05/2016
Your Ref No: SH8440T

Claim Type: Third Party
Accident Date: 06/12/2024
TP Veh Reg No: SH8440T

Estimate Repair Cost to Vehicle No :SLC5387T

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC FRT DOOR LH <i>Revised</i>	995.80	✓
2	1 PC FRT LH DOOR OUTER MOULDING <i>new</i>	68.40	+
3	2 PCS FRT DOOR HINGE LH <i>new</i>	144.80	+
4	1 PC FRT DOOR LH FRAME BLACK TAPE <i>new</i>	58.30	✓
5	1 PC FRT DOOR RUBBER LH <i>new</i>	168.50	+
6	1 PC FRT DOOR LH GLASS REGULATOR ASSEMBLY <i>new</i>	595.50	<i>495</i>
7	1 PC FRT DOOR LOWER INNER PROTECTOR LH <i>new</i>	166.20	+
8	1 PC FRT LH WHEEL ARCH FENDER GARNISH <i>new</i>	188.40	+
9	1 PC FRT LH ROCKER PANEL SIDE SKIRT <i>Revised</i>	464.90	✓
10	1 PC REAR DOOR LH <i>Revised</i>	970.60	✓
11	2 PCS REAR DOOR HINGE LH <i>new</i>	144.80	+
12	1 PC REAR DOOR OUTER MOULDING LH <i>new</i>	56.20	+
13	1 PC REAR DOOR FRAME BLACK TAPE LH <i>new</i>	58.30	✓
14	1 PC REAR DOOR GLASS REGULATOR ASSY LH <i>new</i>	595.50	<i>498</i>
15	1 PC REAR DOOR RUBBER LH <i>new</i>	148.50	+
16	1 PC REAR DOOR LOWER INNER PROTECTOR LH <i>new</i>	146.30	+
17	1 PC REAR LH FENDER ARCH GARNISH <i>new</i>	189.20	✓
		5,160.20	
		Less 20%	
		1,032.04	4,128.16
Special Net			
18	1 SET FRT LH WHEEL ARCH FENDER GARNISH CLIPS <i>new</i>	40.00	+
19	1 SET FRT LH ROCKER PANEL SIDE SKIRT CLIPS <i>new</i>	40.00	+
20	1 SET REAR LH FENDER ARCH GARNISH CLIP <i>new</i>	40.00	+
		120.00	120.00
Labour			
21	1 TO CHECK WIRING	50.00	+
22	1 TO REMOVE AND REFIX FRT DOOR GLASS	100.00	+

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 63591800 FAX: 62320541
ATTN: Motor Claim Department

Estimate No: EST2400490
Date: 09 Dec 2024

Veh Reg No: SLC5387T
Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD 5DR

Chasis No: RU11114175

Reg. Date: 18/05/2016

Your Ref No: SH8440T

Claim Type: Third Party
Accident Date: 06/12/2024
TP Veh Reg No: SH8440T

Estimate Repair Cost to Vehicle No :SLC5387T

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
23	1 TO REMOVE AND REFIX REAR DOOR GLASS	100.00	40
24	1 TO REMOVE AND REFIT DOOR INNER TRIM	120.00	60
25	1 TO SPRAY UNDERSEAL	100.00	+
26	1 TO SPRAY PAINTING	1,200.00	550
27	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	500
		2.870.00	2.870.00
	Total		S\$ 7,118.16
	Add GST @ 9%		640.63
	Total Amount Payable		S\$ 7,758.79

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED FIFTY EIGHT AND CENTS SEVENTY NINE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adam Lim
1/5 18/12/24
05 days
total: 422408
1/5 : 3350 (3350)
Reviewed 25/01/25