



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Supplementary

48 Toh Guan Rd East Enterprise Hub
#02-143/144/145/146/147, Singapore 608586
Tel: 89183288 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2412-786-TG
DATE : 10-Dec-2024
VEHICLE REG. NO. : **SMD329C**
VEHICLE MAKE : HARRIER G GRADE
CHASSIS NO. : JTEKB3GH30J002394
COE : 30/7/2028

TO FIRST CAPITAL

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear End Panel	1	\$ 1,460.50	\$ 1,460.50
2	Rear Floor Panel	1	\$ 1,445.30	\$ 1,445.30
Total Cost Less 20%				\$ (581.16)
Total Spare Parts				\$ 2,324.64
SPECIAL NETT				
Total Special Nett				\$ -
LABOUR				
3	Repair and Replace Affected Accident Parts	1	\$ 300.00	\$ 300.00
4	Spray painting (Rear Floor Panel)	1	\$ 300.00	\$ 300.00
Total Labour				\$ 600.00
Amount Before Excess				\$ 2,924.64
Add GST @ 9%				263.22
Total Amount Payable				\$ 3,187.86

Estimate prepared by: JAMES

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

3134.17
90
1520
615
500
5859.17
415\$4650, 7 days
✱