

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

Supplementary

48 Toh Guan Rd East Enterprise Hub
 #02-143/144/145/146/147, Singapore 608586
 Tel: 89183288 Fax: 67228585
 E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2412-786-TG
 DATE : 10-Dec-2024
 VEHICLE REG. NO. : **SMD329C**
 VEHICLE MAKE : HARRIER G GRADE
 CHASSIS NO. : JTEKB3GH30J002394
 COE : 30/7/2028

TO FIRST CAPITAL

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<u>SPARE PARTS</u>				
1	Rear End Panel	1	\$ 1,460.50	\$ 1,460.50
2	Rear Floor Panel	1	\$ 1,445.30	\$ 1,445.30
Total Cost Less 20%				\$ (581.16)
Total Spare Parts				\$ 2,324.64
<u>SPECIAL NETT</u>				
Total Special Nett				\$ -
<u>LABOUR</u>				
3	Repair and Replace Affected Accident Parts	1	\$ 300.00	\$ 300.00
4	Spray painting (Rear Floor Panel)	1	\$ 300.00	\$ 300.00
Total Labour				\$ 600.00
Amount Before Excess				\$ 2,924.64
Add GST @ 9%				263.22
Total Amount Payable				\$ 3,187.86

820 Bt

XR

820

25% - 615

200

500

Estimate prepared by: JAMES

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

3134.17
 90
 1520
 615
 500
 5859.17
 415\$4650, 7 days
 #