



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070012/Unh3
16 RAFFLES QUAY	Date:	01/07/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8595L	Veh. Inspected	SNL 6382D
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005657MFCT	Excess	\$0.00
Assign From	BETTY WONG	Assign Date	01/07/2024

2. Vehicle Details

Make & Model	SUZUKI LANDY HYBRID (A)	C.C	1797
Engine No.	2ZR2U57747	Year of Reg.	24/07/2023
Chassis No.	ZWR909000699	Colour	BLACK
Odometer	38873 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	GRENLANDER	7
L/H Front Tyre	205/60R16	GRENLANDER	7
R/H Rear Tyre	205/60R16	GRENLANDER	7
L/H Rear Tyre	205/60R16	GRENLANDER	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/06/2024	Inspection Date	01/07/2024
Survey held at	KY AUTO PTE LTD 25 KAKI BUKIT ROAD 4 #05-23 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days