

(08/11/13) . wef

ASS. REC. BY: Marcus

REF:

CS / Fe / 24070012 / Unh3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SNL 63820at Workshop m/s 124

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$188k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C9702

Vehicle: IN / OUT

Date: _____ Person Contacted: RaymondVeh No: SNL 63820 Yr Regn: 24/107/23Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /Truck / Trailer or CAMake: Suzuki Landy Hybrid 1797Colour: Black A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 38873 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: 2WR909000 699Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GreenlanderFront 7 mm Rear 7 mmR/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 26/06/24 D.O.I. 1/7/24

Survey held at _____

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop orRear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Day 2010/7/24 4/5 @ 5-200 inform Raymond(Red. \$12218.20, 707.)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____) S + RS, SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Survey Fee:

Transportation:

TOTAL

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	970Z
Vehicle Details	
Vehicle No.:	SNL6382D
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jul 2024
Vehicle Make:	SUZUKI
Vehicle Model:	LANDY HYBRID 1.8G CVT
Primary Colour:	Black
Manufacturing Year:	2023
Engine No.:	2ZR2U57747
Chassis No.:	ZWR909000699
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$29,162.00
Original Registration Date:	24 Jul 2023
First Registration Date:	24 Jul 2023
Transfer Count:	0
Actual ARF Paid:	\$17,827.00 8913
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jul 2033
PARF Rebate Amount:	\$13,370.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jul 2033
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$120,702.00
COE Rebate Amount:	\$109,345.00
Total Rebate Amount:	\$122,715.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 01 Jul 2024

OK

KY AUTO PTE LTD

25 Kaki Bukit Road 4 #05-23 Synergy Building S417800

Not Allowed
no
1/7/24
9009 6608
1/2 @ 5200
1/2 @ 5200
5 days

M (65) 9807 3304 Mr. Yap

Date: 28/06/2024

F (65)

D.O.A 26/06/2024

Email: kyautosg@gmail.com

SNL6382D - SUZUKI LANDY

Damaged Area: Rear Portion

Parts / Material :

1	Rear bumper	DD	1/25.10	\$	1,654.30	X
2	Rear bumper side retainers @ SGD 96.20	17		\$	192.40	X
3	Rear bumper bracket @ SGD 98.70	NN		\$	197.40	X
4	Rear bumper reinforcement	NS		\$	1,160.30	X
5	Rear bumper sponge	NS		\$	448.90	X
6	Rear bumper reflector o/s @ \$101.40	NN		\$	202.80	X
7	Rear bumper tow garnish o/s	NS		\$	89.60	✓
8	Tailgate	306300	2719.30	\$	2,935.10	✓
9	Tailgate weather strip	701		\$	395.90	✓
10	Tailgate logo (LANDY, Hybrid)	11	115.00	\$	239.20	✓
11	Tailgate lamp LED o/s	17		\$	625.70	X
12	Tailgate inner trimboard	17		\$	928.60	X
13	Tailgate inner trimboard clips	17		\$	80.00	X
14	Tailamp LED o/s	17		\$	955.60	X
15	Rear Panel outer	306500	916.00	\$	1,890.80	?
16	Rear bumper clips	17		\$	120.00	355/17
17	Rear bumper reverse sensot with bracket @ \$265.40	17		\$	1,061.60	72 C
				Parts: \$	13,178.20	

Special Net Items :

Rear number plate	17	\$	60.00	X
Rear pdc sensor o/s	17	\$	80.00	X
Sealant rear window	17	\$	150.00	40 S/N
Acrylic Sealant rear end panel	17	\$	150.00	50 S/N
Total S/N Parts :				\$ 440.00

Labour :

To Remove & Renew Rear Affected Accident Areas	\$	2,000.00	800
To Putty, Spray Paint on Rear Affected Accident Areas	\$	1,500.00	800
To remove and reinstall wiring. Check according to damage.	\$	150.00	20

To conduct computerised wheel alignment
To remove and reinstall passenger seat. ~~Check~~ ^{upholstery} according to damage.

\$ 150.00

\$ 300.00

Total Labour : \$ 3,800.00

TOTAL PARTS : \$ 13,178.20
TOTAL S/N PARTS: \$ 440.00
TOTAL LABOUR : \$ 3,800.00
TOTAL REPAIR COST : \$ 17,418.20

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-562630

152

478236

125

1680

658736

202

5269