

Tea

CD/CT12412949/Tm33

ASSIGNMENT

TOTAL

N/S	O/S
N	



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Co. Reg. No. 09062400M GST Reg. No. IM 90375389 A

Our Ref: WSK/jw/SF-quo
10th December 2024
TP- China Taiping

EB 1133 Z HONDA ODYSSEY

Spare Parts			SS
1	Rear boot.		1171.20 <i>bt</i>
1	Rear boot logo.		36.10 <i>nel</i>
1	Rear boot 'Odyssey' emblem.		52.80 <i>nel</i>
1	Rear boot centre garnish.		314.20 <i>?</i>
1	Rear boot centre garnish chrome moulding.		225.20 <i>cut</i>
2	Rear boot reflectors. @\$421.90		843.80 <i>cut</i>
1	Rear boot lock.		223.40 <i>?</i>
1	Rear boot rubber.		155.20 <i>?</i>
1	Rear windscreen moulding.		203.40 <i>nel</i>
1	Rear bumper.		620.90 <i>del</i>
1	Set rear bumper clips.		42.00 <i>nel</i>
2	Rear bumper side retainers. @\$28.10		56.20 <i>LH-del RH x</i>
2	Rear reverse sensors. @\$400.20		800.40 <i>dis</i>
2	Rear tail lights. @\$821.20		1642.40 <i>LH cut, RH-?</i>
2	Rear bumper lower chrome mouldings. @\$115.20		23.40 <i>LH-?, RH cut</i>
1	Rear support panel.		553.20 <i>?</i>
1	Rear panel inner garnish.		136.10 <i>?</i>
1	Set rear panel inner garnish clips.		21.00 <i>?</i>
1	Rear spare wheel base.		491.20 <i>Rx</i>
1	Rear spare wheel base cover.		360.10 <i>?</i>
1	Rear number plate.		60.00 <i>Snet x</i>
1	Rear windscreen inner seal.		42.00 <i>Snet nel</i>
1	Rear windscreen sealant.		60.00 <i>Snet nel</i>

			8134.20
Less 20%			1594.44

Labour	To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, left rear chassis, rt rear chassis, left rear fender, rt rear fender, renew rear boot, rear support panel, rear lights, rear bumper and assembly.		6539.76
	To respray damaged parts.		1600.00 <i>1000</i>
	To remove, replace rear windscreen.		1350.00 <i>900</i>
	To remove rear seats, rear upholstery, rear garnishes, rear carpets, rear side covers to facilitate repairs and assembly.		180.00 <i>120</i>
	To reseal joints, reinsulate, anti rust panels and assembly.		180.00 <i>60</i>
	To check and reset ECU.		120.00 <i>60</i>
			150.00 <i>100?</i>

			10119.76
			=====

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749/62563561
'wp' 11/12/24 @ 3pm
taufik@lkkauto.com
6-7 days.
1/5 Resurvey after repair