3/5/25, 11:13 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited Our File No: CS/ICS24120150/KVH3E2

10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Date: 05/03/2025

**REFERENCE** 

Insured/Claimant: ENG MEOW KOON Policy No: MPC24P00031800

Date of Loss: 09/12/2024 Nature of Claim: OD Claim No: DMPC2401703H/CT

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMR8400C

Make & Model: HONDA JAZZ, 1.3 CVT (A) Engine No: L13B15000426

Reg. Date: 17/01/2020 (Man. Year: 2019) Chassis No: JHMGK3850LS216896

Colour: Metallic Brown Odometer: 76119 km

Engine Capacity: 1318 cc Market Value/New Car Price: \$\$69,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,133.00	891.00	242.00	21.36
Miscellaneous Items		0.00	0.00	0.00	
Labour		660.00	320.00	340.00	51.52
Paintwork Labour		480.00	400.00	80.00	16.67
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	2,273.00	1,611.00	662.00	29.12
	Approved Total (Overridden) (S\$)		1,250.00		
	(S\$)	2,273.00	1,250.00	1,023.00	45.01
	+ GST 9.00/9.00% (S\$)	204.57	112.50	92.07	45.01
	Nett Amount (S\$)	2,477.57	1,362.50	1,115.07	45.01

**INSPECTION** 

Date of Assignment: 10/12/2024 Present Location: Vin's Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive

Date Inspected: 11/12/2024 Inspected At: #08-09, Sin Ming Auto City

#00-09, Sill Millig Auto City

Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Mar 2025)

Parts: 144 HONDA JAZZ 1.3 CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMR8400C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars Co	ondition	Repairer's	Amount
1	1	NA	*RH HEADLAMP Cu	ıt	410.00 F	*410.00 F
2	1	NA		erviceable	30.00 F	*- F
3	1	NA	*FRONT BUMPER Cr. (WCP)	acked	380.00 F	*380.00 F
4	1	NA	` '	erviceable	10.00 F	*- F
5	10	NA	*FRONT BUMPER CLIPS Ne	ecessary	20.00 F	*20.00 F
6	1	NA	*FRONT RH FENDER (WCP)	epair	180.00 F	*- F
F=Fra	anchise	part.				
				Sub Total (S\$)	1,030.00	810.00
			+ Margin on L,N Items 10.0	00/10.00% (S\$)	103.00	81.00
			т	otal Parts (S\$)	1,133.00	891.00
			Report was unsubmitted during this print-c	out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Pair</u>	ntwork Labour			
1	TO SPRAY PAINTING	New	480.00	400.00
Lab	our Items			
2	TO RESET HEADLAMP SYSTEM	New	280.00	20.00
3	TO REPAIR DAMAGES	New	380.00	300.00
		Gross Labour Cost (S\$)	1,140.00	720.00
	Report w	ras unsubmitted during this print-out.		

< END OF ESTIMATES >