

HUP LIAN HUAT ENGINEERING WORKS

Blk 2 Defu South Street 1 #04-01 Defu Industrial City Singapore 533755
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

M/S : K7 Construction Pte Ltd
 7 Mandai Link #10-13
 Mandai Connection Singapore 728653

TEL: 6292 4006 FAX: 6259 1724
 ATTN:

Your Ref No: K7 CONST PL
 Claim Type: Third Party
 Accident Date: 19/11/2024
 TP Veh Reg No: YQ8593S

Estimate No: ES1601661
 Date: 19 Nov 2024
 Policy No: 5149485446
 Veh Reg No: XD3160X
 Make/Model: MITSUBISHI
 FV51JJD4RDEA
 Chassis No: FV51JJA00382
 Engine No: FV51JJA00382
 Reg. Date:

Not Approved
 23/11/24
 2/s \$3100
 2 days

Estimate Repair Cost to Vehicle No :XD3160X

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 Stand Panel -LH	1,914.29	1 PC	1,914.29	
2 Step Panel -LH	594.41	1 PC	594.41	
3 Step Panel Lower -LH	253.79	1 PC	253.79	
4 Step Panel Under Cover -LH	189.18	1 PC	189.18	
5 Step Alloy Mat Top -LH	520.63	1 PC	520.63	
6 Step Alloy Mat Lower -LH	393.40	1 PC	393.40	
7 Step Panel Reflector -LH	233.53	1 PC	233.53	
8 Front Door Assy -LH	8,832.24	1 PC	8,832.24	
9 Front Door Hinge Upper -LH	227.77	1 PC	227.77	
10 Front Door Hinge Lower -LH	227.77	1 PC	227.77	
11 Front Door Pillar -LH	3,106.53	1 PC	3,106.53	
12 Front Door Inner Pillar -LH	2,346.88	1 PC	2,346.88	
13 Front Door Inner Garnish -LH	336.86	1 PC	336.86	
14 Front Door Frame Rubber Seal -LH	549.26	1 PC	549.26	
15 Front Door Lamp -LH	361.81	1 PC	361.81	
16 Rear Corner Panel Handle -LH	837.55	1 PC	837.55	
			20,925.90	
		Less 25%	5,231.48	15,694.45
Labour				
17 Labour to remove & refit front door & realignment & transfer parts .	100.00	1 JOB	100.00	
18 Labour to remove & refit door lamp & connect wire .	180.00	1 JOB	180.00	
19 Labour to knock & renew & weld & refit all affected area .	950.00	1 JOB	950.00	
20 To rust proofing at accident affected area .	400.00	1 JOB	400.00	
21 To spray & painting at accident affected area .	850.00	1 JOB	850.00	
			2,480.00	2,480.00

4501.32

200
 300

HUP LIAN HUAT ENGINEERING WORKS

Blk 2 Defu South Street 1 #04-01 Defu Industrial City Singapore 533755
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

M/S : K7 Construction Pte Ltd
 7 Mandai Link #10-13
 Mandai Connection Singapore 728653

TEL: 6292 4006 FAX: 6259 1724
 ATTN:

Your Ref No: K7 CONST PL
 Claim Type: Third Party
 Accident Date: 19/11/2024
 TP Veh Reg No: YQ8593S

Estimate No: ES1601661
 Date: 19 Nov 2024
 Policy No: 5149485446
 Veh Reg No: XD3160X
 Make/Model: MITSUBISHI
 FV51JJD4RDEA
 Chassis No: FV51JJA00382
 Engine No: FV51JJA00382
 Reg. Date:

Estimate Repair Cost to Vehicle No :XD3160X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 18,174.45
			Add GST @ 9%	1,635.70
			Total Amount Payable	S\$ 19,810.15

TOTAL: SINGAPORE DOLLAR NINETEEN THOUSAND EIGHT HUNDRED TEN AND CENTS FIFTEEN ONLY

**For HUP LIAN HUAT ENGINEERING
WORKS**

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: