

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Not Authorized
11 Sep @ 5700h
Returning After 6 days

Vehicle Number : SNK 1976D

Date: 01.12.24

S/N Parts Description

Unit Price Amt

1	Rear bootlid		R	\$2,028.30	X
2	Rear bootlid emblem		me	\$55.00	—
3	Rear bootlid E200 emblem		me	\$78.00	—
4	Rear bootlid CGI emblem		me	\$85.00	—
5	Rear bootlid reflector RH		su	\$566.20	X
6	Taillamp RH		Br	\$738.40	✓
7	Taillamp lower retainer RH		cm	\$78.00	—
8	Rear bumper assy		Br/cm	\$1,680.00	✓
9	Rear bumper reinforcement		R	\$678.00	X
10	Rear bumper retainer X 2	olscnt \$63.00		\$126.00	✓
11	Rear bumper mldg		me	\$146.00	—
12	Rear fender RH		Br	\$2,640.00	—
13	Rear fender inner garnish RH		cm	\$268.20	—
14	Rear fender shield RH		su	\$234.00	X
15	Rear windscreen mldg		me	\$234.00	—
16	Rear end panel	109	R	\$1,228.00	X
17	Rear end panel top garnish		su	\$245.00	X
Special Nett					
1	Rer bumper clips		me	\$50.00	✓
2	Rear windscreen sealant		me	\$60.00	405n
3	Rear fender shield clips		me	\$80.00	X

Labour

1	To remove and refit damaged parts, cut/weld damaged areas.	\$1,000.00	700l
2	To spray paint on affected areas.	\$1,200.00	800l
3	Check wiring	\$50.00	20l
4	Tuff coating	\$120.00	30l
5	To remove and refit rear windscreen	\$120.00	✓
6	To remove and refit rear ganishes etc.	\$180.00	100l

\$2,670.00

Page 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: