



HxGN EAM

Accident Report

User	LIMING@SBSTRANSIT.COM.SG
Report Created	Feb 18, 2025

Certificate of Bus Repair

Depot	AM	Bus No	SBS5062P
Driver	60883	Accident Date	Dec 8, 2024
Work Order No	1662534	Case No / AR No	24467 / AR-2024-6658

Date IN Dec 8, 2024

Date Out

Feb 13, 2025

Registration Date	Model/Manufacturer	Chassis No.
Mar 26, 2010	Scania KUB4X2(EEV), SD, AC, 2 Axle	YS2K4X20001867405

Stock Code	Description	Quantity	Total Material Cost (\$)
18205016 N	HOSE CLAMP;CHARGE AIR PIPE N	4	\$60.60
18202044 N	FAN COVER;FAN N	1	\$76.63
18205018 R	CHARGE AIR COOLER. XR ^ R	1	\$659.50
18230148 N	HYDRAULIC HOSE;OIL COOLER. N	1	\$41.53
38491042 N	HOSE;SILENCER;COMPR MTG N	1	\$33.97
18205017 N	HOSE;CHARGE AIR COOLER N	2	\$342.88
30122052 N	VERTICAL PILLAR @ KL+KR;SIDE FRAME N	1	\$228.60
18081019 N	PRESSURE SWITCH;AIR INTAKE N	1	\$91.05
18205028 N	CHARGE AIR PIPE;CHARGE AIR COOLER N	1	\$378.15
18230132 N	HYDRAULIC OIL TANK;FLUID RESVR. N	1	\$309.46
18081025 N	AIR CLEANER ASSY N	1	\$158.72
18141124 N	INTAKE MANIFOLD;AIR PIPE;ENG N	1	\$534.99
91011008 N	REVERSE BUZZER;24V;97DBA N	1	\$12.00
38501062 N	VIBRATION INSULATOR.RADIATOR.SUPPN N	4	\$95.36
18182035 N	HOSE;OIL COOLER;TUBE;K N	1	\$35.98

Stock Code	Description	Quantity	Total Material Cost (\$\$)
30122104 N	PVC HOSE 2;AIR CLEANER BX ASSY N	2	\$77.14
99001048	SIKAFLEX 255 EXTRA BLACK (400 ML/SAU)	20	\$240.00
18205029 N	V-CLAMP;CHARGE AIR COOLER N	1	\$28.18
30122113 N	RADIATOR GRILL JL~KL;SIDE PANEL ASSY N	1	\$612.00
30122131 N	COMPARTMENT HINGE RHS 1@ JL N	1	\$122.10
30311403 N	BUMPER.REAR.F/G.C&D SERIES N	1	\$305.00
30122005 N	GAS JACK 0400N;RR ENG DOOR N	2	\$52.00
30122484 N	ENGINE REAR VENT COVER N	1	\$65.00
38501029 N	HOSE CLAMP;TUBES;RAD N	2	\$4.74
18081029 N	VALVE.AIR INTAKE.AIR CLEANER N	1	\$33.26
30122140 N	INSULATION HOLDER 06;1.0MM ALUM SHEET N	2	\$48.84
30122145 N	ALUM WIRE MESH;ENG DR;1PC=1.8M N	1	\$172.60
91406025 N	EDS HANOVER;REAR SIGN;17X32 N	1	\$459.00
30541669 N	REFLEX REFLECTOR N	2	\$2.70
30541739 N	LED TAIL/STOP LAMP N	1	\$97.20
30541741 N	LED REVERSE LAMP N	1	\$105.60
30541740 N	LED INDICATOR LAMP N	2	\$204.38
30122005 N	GAS JACK 0400N;RR ENG DOOR N	2	\$52.00
30541765 N	LED LICENSE PLATE LAMP N	2	\$42.80
38241020	COVER PLATE;LH;NOISE SHIELD;ENG COMPT N	1	\$139.18

Stock Code	Description	Quantity	Total Material Cost (\$\$)
N			
38501048 N	LATCH HOOK;FRT GRILLE PANEL;CL N	4	\$23.20
30122089 N	MOUNTING BRKT;5MM STEEL;RR FRAME N	1	\$34.40
30117430 N	REAR WINDSCREEN..SN C&D N	1	\$170.00
30122057 N	DOOR FRAME;ENG COMPARTMENT DR;ALUM N	1	\$369.00
30122058 N	REAR DOOR;F/GLASS;C & C+ SERIES N	1	\$523.00
30122114 N	DOOR FRAME JL~KL;RAD.GRILL N	1	\$321.42
30122158 N	ATTACHMENT BRACKET BOTTOM;RR FRAME N	1	\$57.14
30122129 N	INSULATION 01;CPSS25;25MMX1MX2M;WIRING N	1	\$149.13
30122130 N	COMPARTMENT HINGE LHS 1@ HL N	1	\$122.10
30122137 N	INSULATION HOLDER 01;1.0MM ALUM SHEET N	1	\$33.42
30122139 N	INSULATION HOLDER 04;1.0MM ALUM SHEET N	4	\$77.12
30122138 N	INSULATION HOLDER 03;1.0MM ALUM SHEET N	2	\$74.20
38541196 N	CABLE HARNESS;ENG MGMT SYS N	1	\$95.65
18230247 N	PIPE ASSEMBLY.HYDRAULIC PUMP N	1	\$1,228.10
38241038 N	BRACKET.ENGINE SUSPENSION. N	-1	-\$444.34
18205015 N	CHARGE AIR PIPE;CHARGE AIR COOLER N	1	\$435.41
38311072 N	FRAME;RADIATOR;SUSPN N	1	\$891.07
38241038 N	BRACKET.ENGINE SUSPENSION. N	1	\$444.34
18141194	HOSE CLAMP.INTAKE MANIFOLD.AIR PIPE N	2	\$2.20

Stock Code	Description	Quantity	Total Material Cost (\$\$)
N			
30750518 N	PILLAR REPAIR KIT N	2	\$1,256.90
30122080 N	REAR DOME;F/GLASS;SN SERIES C N	1	\$1,200.00
30122090 N	REAR FRAME PILLAR;RR FRAME N	1	\$153.00
30122190 N	ATTACHMENT BRACKET MID;RR FRAME N	1	\$162.00
30122485 N	ENGINE REAR VENT COVER BRACKET N	4	\$145.60
30122498 N	VANITY PANEL @ EL;EXIT DR N	1	\$75.00
38501089 N	HOSE;PIPES & HOSES N	1	\$12.51
38541195 N	MASS FLOW SENSOR;ENG MGMT SYS N	1	\$242.17
18081020 N	UNION ASSY;AIR INTAKE N	1	\$14.54
18230151 N	HOSE;HYDRAULIC PUMP. N	1	\$13.29
30122565 N	CLIP.PVC HOSE SIZE 9 N	1	\$4.50
38541291 N	GASKET;CABLE HARNESS;EMS INJ SYS N	1	\$2.31
38321003 N	PLASTIC TUBE;OD6;A/C/S. N	20	\$61.20
38421112 N	INSERT CONNECTION;AIR DRYER N	1	\$10.13
38501074 N	STRIP;RADIATOR. N	8	\$79.68
38006004 N	HOSE CLAMP;23-35MM;OIL COOLER N	5	\$9.85
38311068 N	FRAME;RADIATOR SUSPENSION N	-1	-\$220.00
18141160 N	ELBOW UNION;8M10X1K;TURBO CHARGER N	1	\$10.99
38501028	FRAME;EXPN-TANK W/CONN N	1	\$79.39

Stock Code	Description	Quantity	Total Material Cost (S\$)
N 38311068 N	FRAME;RADIATOR SUSPENSION N	1	\$220.00
N 38501054 N	RADIATOR ASSY. SCANIA EU4 & 5 XR ^ N	1	\$831.46
N 38421015 N	VALVE.RELAY.PARKING VALVE N	1	\$116.96
N 38421135 N	HAND CONTROL UNIT;PARKING BRAKE VALVE N	1	\$310.28
N 38501127 N	LEVEL PIPE ASSY.LEVEL GLASS N	1	\$31.02
N 38461098 N	CLIP;ADJUSTABLE STRG COLUMN. N	1	\$2.18
N 38541290 N	SLEEVE;CABLE HARNESS;EMS INJ SYS N	1	\$11.54

TOTAL FOR PARTS		S\$	15,366.20
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	Workshop Labour	S\$	188.00
2	Contractor's Repair Charges	S\$	7,680.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST		S\$	7,868.00
Repair cost of Advertisement / Livery		S\$	0.00
TOTAL DAMAGE		S\$	23,234.20
Overheads		S\$	6,970.26
Towing Charges		S\$	158.00
Repair Period : 8.00 Days		Loss of Use	S\$ 3,264.80
TOTAL LOSS		S\$	33,627.26