

MS CAR AUTO PTE LTD

8 KAKI BUKIT AVENUE 4 #01-07 PREMIE @KAKI BUKIT
SINGAPORE 415875

TO	: 1ST CAPITAL	DATE	1/7/2024
VEHICLE NO	: SFX3111X (2016)		
VEHICLE MODEL	: MITSUBISHI OUTLANDER		
CHASSIS NO	: JMYXTGF3WG2004461		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE LAMP <i>New</i>	2	\$ 58.00	\$ 116.00
2	REAR BUMPER <i>Dehnd</i>	1	\$ 816.00	\$ 816.00
3	REAR BUMPER SIDE HOLDER <i>New</i>	2	\$ 32.00	\$ 64.00
4	REAR BUMPER IMPACT BRACKET <i>PH 3rd</i>	2	\$ 105.00	\$ 210.00
5	REAR BUMPER LOWER GARNISH <i>New</i>	1	\$ 289.00	\$ 289.00
6	REAR BUMPER REFLECTOR <i>New</i>	2	\$ 98.00	\$ 196.00
7	REAR END PANEL <i>Dehnd</i>	1	\$ 526.00	\$ 526.00
8	REAR END PANEL TOP GARNISH <i>New</i>	1	\$ 146.00	\$ 146.00
9	REAR END PANEL BUZZER <i>New</i>	1	\$ 182.00	\$ 182.00
10	REAR END PANEL ANTENNA SENSOR <i>New</i>	1	\$ 196.00	\$ 196.00
11	TAILLAMP <i>New</i>	2	\$ 506.00	\$ 1,012.00
12	TAILGATE <i>Dehnd</i>	1	\$ 884.00	\$ 884.00
13	TAILGATE LOCK <i>New</i>	1	\$ 385.00	\$ 385.00
14	TAILGATE WEATHERSTRIPE <i>New</i>	1	\$ 192.00	\$ 192.00
15	TAILGATE REFLECTOR <i>New</i>	2	\$ 397.00	\$ 794.00
16	TAILGATE INNER TRIM BOARD <i>Chehnd</i>	1	\$ 352.00	\$ 352.00
17	TAILGATE OUTER GARNISH <i>New</i>	1	\$ 446.00	\$ 446.00
18	TAILGATE GLASS MOULDING <i>New</i>	1	\$ 161.00	\$ 161.00
19	MITSUBISHI LOGO <i>New</i>	1	\$ 41.00	\$ 41.00
20	OUTLANDER EMBLEM <i>New</i>	1	\$ 86.00	\$ 86.00
21	MIVEC EMBLEM <i>New</i>	1	\$ 52.00	\$ 52.00
22	FLOOR PANEL <i>New</i>	2	\$ 895.00	\$ 895.00
23	FLOOR PANEL TOP BOARD <i>New</i>	1	\$ 455.00	\$ 455.00
24	TOOLS TRAY <i>New</i>	1	\$ 289.00	\$ 289.00
25	SPARE TYRE CARRIAGE <i>New</i>	1	\$ 386.00	\$ 386.00
26	REAR FENDER INNER TRIM <i>New</i>	2	\$ 676.00	\$ 1,352.00

TOTAL PRICE: \$ 10,523.00
LESS 10% \$ 1,052.30
SUB TOTAL PRICE: \$ 9,470.70

3270
2943

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>New</i>	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER <i>New</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00
4	REAR BUMPER STICKER WRAP <i>New</i>	1	\$ 450.00	\$ 450.00
5	REVERSE SENSOR <i>New</i>	1 SET	\$ 280.00	\$ 280.00
6	REAR END PANEL TOP GARNISH CLIPS <i>New</i>	1 SET	\$ 20.00	\$ 20.00
7	REAR END PANEL SEALANT <i>New</i>	1	\$ 60.00	\$ 60.00

8	TAILGATE INNER TRIM BOARD CLIPS	Nec
9	TAILGATE OUTER GARNISH CLIPS	Nec
10	TAILGATE GLASS SEALANT	Nec
11	TAILGATE STICKER WRAP	Nec
12	CYCLE & CARRIAGE LOGO	Nec
13	FLOOR PANEL INSULATION PAD	
14	REAR FENDER INNER TRIM BOARD CLIPS	
15	REAR CAMERA	

1 SET	\$	30.00	\$	30.00
1 SET	\$	20.00	\$	20.00
1	\$	60.00	\$	60.00
1	\$	450.00	\$	450.00
1	\$	45.00	\$	45.00
1	\$	280.00	\$	280.00
2 SET	\$	30.00	\$	60.00
1	\$	480.00	\$	480.00

TOTAL : \$ 2,325.00

LABOUR

	JOB
1	PANEL BEATING, REMOVE AND REFIT PARTS
2	SPRAY PAINTING TO AFFECTED AREA
3	WIRING CHECK
4	TO APPLY TUFF COAT
5	TO REMOVE REVERSE SENSOR
6	TO REMOVE UPHOLSTRY
7	TO REMOVE REAR CAMERA
8	TO TRANSFER TAILGATE FITTINGS
9	TO REMOVE TAILGATE GLASS

TOTAL:

PRICE	ADJUSTED COST	APPROVED
1,600.00	800	
1,400.00	800	
50.00	30	
150.00	60	
100.00	50	
150.00	60	
100.00	50	
150.00	60	
180.00	120	

3,880.00

ESTIMATE REPORT

TOTAL PARTS COST:	\$	11,795.70
TOTAL LABOUR COST:	\$	3,880.00
TOTAL REPAIR COST:	\$	15,675.70

total 6083
H/S: 481C.

OT Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/a. spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

481C