

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24120158/Anh3e2(N)	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	20/06/2025	
	ATTN: EILEEN LEI	=		Code:	INC	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMS 9892D	Veh. Inspected	k	SME 2403C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1307866-001	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		11/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	SUBARU FORESTER	c.c		1995	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	JF1SJ5KC5JG112768	Colour		BLUE	
	Odometer	136063 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/60 R17	BRIDGESTONE		6 mm	
	L/H Front Tyre	225/60 R17	BRIDGESTONE		6 mm	
	R/H Rear Tyre	225/60 R17	BRIDGESTONE		6 mm	
	L/H Rear Tyre	225/60 R17	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
	DAMAGES SEE DI	ETAILS.				
5.	5. General Information					
J.	Accident Date	06/12/2024	Inspect Date /	Time	16/12/2024 (04:49 PM)	
	Survey held at	ADVANCE AUTO GARAGE	ilispect Date /	Tillie	10/12/2024 (04.43 1 W)	
	Survey field at	23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					
	•					