

Performance Motors

BMW Dealer



Supplementary

Estimate No. : **b1 72044**
Date Estimated : **07/12/2024**
Prepared By : **Chua Kee Sin**

Page No. :

- ESTIMATE REPAIR FOR -

Ng Wai Hung Andrew
14 Narooma Road

Singapore 298309

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNC9083U	WBA22AT020CH52494	13/08/2021	430i Convertible	16028

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To remove PDC assembly, replace damaged parts include reconnecting to bumper and conducting checks for proper function	177.00		177.00 /

* To replace front light electronics control unit, RH LED module daytime driving light include programming and conducting tests for proper function	280.00		280.00 /
---	--------	--	----------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# GRILLE AIR INLET MIDDLE (M)	119.35	1.00	0.00	119.35 <i>dis</i>
# AIR DUCT WITH AIR FLAP CONTROL BOTTOM	343.95	1.00	0.00	343.95 <i>cra</i>
# FRT RH BRAKE AIR DUCT	59.20	1.00	0.00	59.20 <i>de</i>
# HIGH PITCH HORN	94.20	1.00	0.00	94.20 <i>dis</i>
# FRT LIGHT ELECTRONICS CONTROL UNIT	996.90	1.00	0.00	996.90 <i>dis</i>
# RH LED MODULE DAYTIME DRIVING LIGHT	256.50	1.00	0.00	256.50 <i>dis</i>

SUPPLEMENTARY ITEMS

Total Labour :	457.00
Total Parts :	1,870.10
Total Labour & Parts (before GST) :	2,327.10

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W