



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2503042

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN:SERENE LER

INV Date 23/04/2025
Reference CD/FCI24120162/Tpa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJA 7370L
Insured Veh. SHD 3689C
Claim No. D24010797MFCT/CTPL/TPD 2
Policy No. D-24101861MFCT
Accident Date 09/12/2024
Inspection Date 06/01/2025

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN:SERENE LER			Ref: CD/FCI24120162/Tpa3q2(N) Date: 23/04/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3689C	Veh. Inspected	SJA 7370L
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24010797MFCT/CTPL/TPD 2	Excess (\$)	0.00
	Assign From	SERENE LER	Assign Date	06/01/2025
2. Vehicle Particulars & Condition				
	Make & Model	INFINITI QX50	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	3PCMANJ55Z0552464	Colour	BRONZE
	Odometer	51897 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/45 R20	BRIDGESTONE	6 mm
	L/H Front Tyre	255/45 R20	BRIDGESTONE	6 mm
	R/H Rear Tyre	255/45 R20	BRIDGESTONE	6 mm
	L/H Rear Tyre	255/45 R20	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/12/2024	Inspection Date	06/01/2025
	Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 7370L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER SET -RR (SN)	TO REPAIR SEE LABOUR	1,905.60	-
1	FASCIA -REAR BUMPER L (SN)	CUT	1,270.50	1,143.45
1	BRACKET -BUMPER RH (SN)	NECESSARY	123.00	110.70
1	MLDG-FILLET RHR QTR (SN)	CUT	328.00	295.20
1	MLDG-FILLET RHR DOOR (SN)	CUT	328.00	295.20
1	WHEEL ROAD AL (SN)	DENTED	2,991.30	2,692.17
1	SENSOR UNIT TIRE P (SN)	NECESSARY	193.80	174.42
10	CLIP (SN)	NECESSARY	32.00	28.80
			7,172.20	4,739.94
	<u>LABOUR</u>			
	TO REPLACE RR BUMPER ,RR QTR ARC MLDG ,RR DOOR ARC MLDG ,RELATED PARTS.INCLUSIVE OF THE REPAIR OF BUMPER SET -RR.		2,700.00	900.00
	TO PRIME & SPRAY PAINT RR BUMPER ,RH QTR PANEL .		2,550.00	850.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		498.00	498.00
	TO REPLACE RHR ALLOY RIM .		100.00	100.00
	WHEEL ALIGNMENT.		280.00	280.00
			6,128.00	2,628.00
GRAND TOTAL			13,300.20	7,367.94

RECOMMENDED COST OF REPAIRS			7,367.94
------------------------------------	--	--	-----------------

Report Ref No. CD/FCI24120162/Tpa3q2(N)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SJA 7370L



PHOTOGRAPHS FOR VEHICLE NO. : SJA 7370L



PHOTOGRAPHS FOR VEHICLE NO. : SJA 7370L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 6)

PHOTOGRAPHS FOR VEHICLE NO. : SJA 7370L



PHOTOGRAPHS FOR VEHICLE NO. : SJA 7370L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 6 of 6)

PHOTOGRAPHS FOR VEHICLE NO. : SJA 7370L



PHOTOGRAPHS FOR VEHICLE NO. : SJA 7370L



PHOTOGRAPHS FOR VEHICLE NO. : SJA 7370L



PHOTOGRAPHS FOR VEHICLE NO. : SJA 7370L



PHOTOGRAPHS FOR VEHICLE NO. : SJA 7370L

