

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 48992400W

Vehicle Number: ED9770X

Vehicle Model : Toyota Voxy Hybrid 1.8SZ CVT

Manufacturing Year : 2023

Vehicle Chassis : ZWR900103287

S/N.	Item Description	Amount (\$)	
1	Rear Boot / <i>DD</i>	\$ 2,237.04	1985 /
2	"Hybrid" Logo / <i>MC</i>	\$ 141.59	80 /
3	Rear Boot Lamp (RH) / <i>BR</i>	\$ 1,146.19	690 /
4	Taillamp x 2 pcs (<i>RH</i>) / <i>BR</i> (<i>LH</i>) X <i>nn</i>	\$ 2,624.27	881 /
5	Rear Boot Trimboard / <i>BR</i>	\$ 778.80	/
6	Rear Boot Trimboard Clip x 1 set / <i>MC</i>	\$ 2 ^o / 108.23	
7	Rear Boot Lock / <i>MC</i>	\$ 413.31	364 /
8	Rear Boot Catch X <i>nn</i>	\$ 85.60	
9	Rear Boot Weatherstrip / <i>TR</i>	\$ 484.33	/
10	Rear Boot Shock Absorber x 2 pcs X / <i>Janned</i>	\$ 772.11	/
11	Rear Number Plate Top Garnish X <i>nn</i>	\$ 851.24	
12	Rear Number Plate Lamp X <i>nn</i>	\$ 259.94	
13	Rear Bumper / <i>BR</i>	\$ 2,491.65	1086 /
14	Rear Bumper Reflector x 2 pcs (<i>RH</i>) / <i>BR</i> (<i>LH</i>) X <i>nn</i>	\$ 394.26	197.13 /
15	Rear Bumper Clip x 1 set / <i>MC</i>	\$ 3 ^o / 75.35	
16	Rear Bumper Side Retainer (RH) / <i>BR</i>	\$ 171.07	132 /
17	Rear Bumper Support No.1 (RH) / <i>BR</i>	\$ 141.70	115 /
18	Rear Corner Garnish (RH) / <i>CRU</i>	\$ 239.79	/
19	Rear Corner Garnish Bracket (RH) / <i>BR</i>	\$ 181.30	/
20	Rear Fender x 2 pcs X <i>R</i>	\$ 3,654.46	
21	Rear Fender Inner Trimboard x 2 pcs (<i>RH</i>) / <i>CRU</i> (<i>LH</i>) / <i>BR</i>	\$ 1,549.14	/
22	Rear Fender Inner Trimboard Clip x 2 set / <i>MC</i>	\$ 4 ^o / 100.00	
23	Rear Cooling Unit Assy (RH) / <i>BR</i>	\$ 4,746.00	/
24	End Panel / <i>DD</i>	\$ 623.44	/
25	End Panel Top Garnish / <i>CRU</i>	\$ 234.16	/
26	Spare Tyre Compartment Panel / <i>DD</i>	\$ 787.24	/
27	Spare Tyre Sponge / <i>BR</i>	\$ 162.63	/
28	Rear Jack Tool Box Cover / <i>CRU</i>	\$ 199.91	/
29	Rear Jack Tool Bracket / <i>BT</i>	\$ 151.40	/
30	Rear Deck Top Board / <i>BR</i>	\$ 896.35	/
31	Rear Blind Spot Monitor Sensor (RH) / <i>BR</i>	\$ 1,446.91	/

32	Rear Electrical Key Antennae / GR	\$	107.44
33	Rear Boot Top Spoiler Clip x 1 set / AL	\$ 71	50.00
Tailgate absorb R4 JLLH - jmmord			
have in the estimate 11			
Total :		\$	28,306.85
Less 25% :		\$ 75%	5,661.37
Amount :		\$	22,645.48

19,001.98
- 25%
14,259.81

S/N	Special Nett Item	Amount (\$)
1	Reverse Sensor x 2 pcs / GR	\$ 688.00
2	End Panel Sealant / MR	\$ 30 100.00
3	Windscreen Sealant / PRC	\$ 40 80.00
Amount :		\$ 868.00

560

630

Labour	Amount (\$)
To conduct computer diagnostic and resetting (calibration bill)	\$ 380.00
To check rear electrical wiring system	\$ 30 120.00
To remove & install rear windscreen	\$ 120 180.00
To remove and reinstall reverse sensors	\$ 30 80.00
To transfer tailgate component to new tailgate	\$ 50 180.00
To remove & install rear cooling unit and refill a/c gas	\$ 120 280.00
To remove & install rear cabin seats to facilitate repair	\$ 80 120.00
To spray anti-rusting coating on affect areas	\$ 30 150.00
To remove & install interior garnishes, trims etc to facilitate repair	\$ 80 280.00
To straighten, repair, realign on rear chassis, repair rear fenders, and replace damaged parts	\$ 1400 3,800.00
To spray paint on front affected areas	\$ 1200 1,800.00
Labour Total :	\$ 7,370.00
Total (Parts & Labour)	\$ 30,883.48

500

3640

STOR (LKK)

12 / 12 / 24, 4.1%

MR

P/P

by AL by

12 d/s

= 18,520.81