

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24120168/NNH3M4**Date:** 26/12/2024**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT102015		
Claimant Vehicle No :	SHA7522P	Insured Vehicle No :	SLZ5353U		
Date of Loss:	09/12/2024	Nature of Claim:	TP	Claim No:	M2407277

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7522P	Engine No:	G4LEKU414693
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU191427
Reg. Date:	30/10/2020 (Man. Year: 2019)	Odometer:	435744 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,823.12	645.52	3,177.60	83.12
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	2,710.00	1,980.00	730.00	26.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,545.12	2,637.52	3,907.60	59.70
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	6,545.12	2,100.00	4,445.12	67.92
+ GST 9.00/9.00% (S\$)	589.06	189.00	400.06	67.91
Nett Amount (S\$)	7,134.18	2,289.00	4,845.18	67.92

INSPECTION

Date of Assignment:	12/12/2024 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang) COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969
Date Inspected:	11/12/2024 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Dec 2024)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7522P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR PANEL LH	Repair	2,147.90 FL	*- FL
2	1		*REAR FENDER LH	Repair	1,768.30 FL	*- FL
3	1		*REAR BUMPER RETAINER LH	Serviceable	55.80 FL	*- FL
4	1		*REAR DOOR PROTECTOR LH	Scratched	125.10 FL	*125.10 FL
5	1		*FRONT DOOR PROTECTOR LH	Scratched	110.00 FL	*110.00 FL
6	1		*FRONT DOOR COMFORT LOGO STICKER	Necessary	75.00 FS	*75.00 FS
7	1		*REAR DOOR COMFORT APP LOGO STICKER	Necessary	80.00 FS	*80.00 FS
8	1		*REAR WHEEL CAP COVER LH	Scratched	346.80 FL	*346.80 FL
9	1		*FENDER PETROL STICKER LH	Necessary	25.00 FS	*25.00 FS
					Sub Total (S\$)	4,733.90 761.90
					- List Item Discount on L Items 20.00/20.00% (S\$)	910.78 116.38
					Total Parts (S\$)	3,823.12 645.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,330.00	1,140.00
2	SPRAY PAINTING	New	1,200.00	840.00
3	REMOVE/REFIX DOOR PARTS	New	90.00	0.00
4	REMOVE/REFIX REAR UPHOLSTERY LH	New	90.00	0.00
Gross Labour Cost (\$\$)			2,710.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >