

ASS. REC. BY:

REF:

ICS/CS/ICS24120169/knh3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD/TP/WS/TP RES/QD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vsh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 821K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SPP 14D Yr Regn: 08.16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or A)Make: Hyundai Elantra C.C. 1591Colour: Black A/C: Insured / Std / NI / NASp. Reading: 70818 T/Radio: Insured / Std / NI / NAEng/No: 70818C/No: KM14D841CMTU 181219Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD / RIM orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 5/12/24

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 13/12/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/12 @ 800. Calm (Red. \$ 2121, 72%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC24A00323001	Date of Loss:	05/12/2024
Vehicle Reg. No.:	SDP14D	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GOH HWEE NGEE MICHELLE		
Make/Model:	HYUNDAI ELANTRA, 1.6 (A)	Vehicle Reg. Date:	16/08/2016
Vehicle Colour:	BLACK	Chassis No:	KMHD841CMHU161219
Engine No:	G4FGGU169394		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	2 days		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

Not Notified
11 Day & 800k
Running After Pain
Ex Waive

COST OF CLAIMS

	Amount
Parts	1,001.00
Miscellaneous Items	100.00
Labour	1,820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,921.00
+ GST 9.00% (S\$)	262.89
Nett Amount (S\$)	3,183.89

This claim is handled by: ADMIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Dec 2024)
Parts: 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDP14D)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	0.00	0.00	*330.00 F ✓
2	2		*REAR BUMPER SIDE RETAINER	0.00	0.00	*44.00 F X
3	1		*REAR BUMPER REFLECTOR LH	0.00	0.00	*28.00 F X
4	1		*REAR BUMPER REFLECTOR RH	0.00	0.00	*28.00 F X
5	1		*REAR BUMPER LOWER	0.00	0.00	*125.00 F X
6	1		*REAR REINFORCEMENT BAR	0.00	0.00	*160.00 F 2
7	1		*REAR END PANEL	0.00	0.00	*160.00 F X
8	1		*REAR END PANEL TOP GARNISH	0.00	0.00	*35.00 F X

F=Franchise part.

Sub Total (S\$) **910.00**
+ Margin on L,N Items 10.00% (S\$) 91.00

Total Parts (S\$) **1,001.00**

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	REAR BUMPER CLIPS SET
2	1	REAR FENDER INNER SHIELD RH SET

nn 50.00 ✓
nn 50.00 X

Sub Total (S\$) 100.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	SPRAY PAINT ON ALL AFFECTED AREA
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA
3	TO CHECK WIRING SYSTEM & LIGHT
4	TO APPLY ANTI RUST TREATMENT

New 200l 800.00
New 200l 800.00
New 100.00 10l
New nn 120.00 X

Gross Labour Cost (S\$) 1,820.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: