

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC24A00323001	Date of Loss:	05/12/2024
Vehicle Reg. No.:	SDP14D	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GOH HWEE NGEE MICHELLE		
Make/Model:	HYUNDAI ELANTRA, 1.6 (A)	Vehicle Reg. Date:	16/08/2016
Vehicle Colour:	BLACK	Chassis No:	KMHD841CMHU161219
Engine No:	G4FGGU169394		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10 2 days		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

Not Authorized
11 Amp & 800p
Recovery After Paint
Ex Waive

COST OF CLAIMS

	Amount
Parts	1,001.00
Miscellaneous Items	100.00
Labour	1,820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,921.00
+ GST 9.00% (S\$)	262.89
Nett Amount (S\$)	3,183.89

This claim is handled by: ADMIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Dec 2024)
Parts: 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDP14D)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	0.00	0.00	*330.00 F ✓
2	2		*REAR BUMPER SIDE RETAINER	0.00	0.00	sn *44.00 F X
3	1		*REAR BUMPER REFLECTOR LH	0.00	0.00	*28.00 F X
4	1		*REAR BUMPER REFLECTOR RH	0.00	0.00	*28.00 F X
5	1		*REAR BUMPER LOWER	0.00	0.00	sn *125.00 F X
6	1		*REAR REINFORCEMENT BAR	0.00	0.00	*160.00 F Z
7	1		*REAR END PANEL	0.00	0.00	sn *160.00 F X
8	1		*REAR END PANEL TOP GARNISH	0.00	0.00	sn *35.00 F X
Sub Total (\$\$)						910.00
+ Margin on L,N Items 10.00% (\$\$)						91.00
Total Parts (\$\$)						1,001.00

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	REAR BUMPER CLIPS SET	nn 50.00 ✓
2	1	REAR FENDER INNER SHILED RH SET	nn 50.00 X
Sub Total (S\$)			100.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	SPRAY PAINT ON ALL AFFECTED AREA	New	200l 800.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	200l 800.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	100.00 10l
4	TO APPLY ANTI RUST TREATMENT	New	nn 120.00 X
Gross Labour Cost (S\$)			1,820.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: