

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 13 Dec 2024

**Preliminary Advice**

Vehicle No	: SDP14D	Accident Date	: 05/12/2024
Make	: HYUNDAI ELANTRA	Policy No.	: MPC24A00323001
Assignment Date	: 12/12/2024	Excess	: S\$0.00
Date of Inspection	: 13/12/2024	Est. Duration of Repair	: 2
Inspection At	: ACCORD AUTO SERVICES PTE LTD (HQ) 10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,921.00
Revised Amount	:S\$	823.00
Check Items (Estimated)	:S\$	313.50
Total	:S\$	1,136.50

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	21,000.00
COE / PARF Rebate	:S\$	18,195.00
Salvage Value	:S\$	
Margin for Repair	:S\$	2,805.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The vehicle repair on Lump Sum basis.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.