

Acknowledged by Repairer
Signature:
Date:

	Balance carried forward.		9,192.53
1 set	Reverse sensor	s.nett	220.00
1 pc	Rear windscreen sealant	s.nett	80.00
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		2,500.00
	To check wiring system.		80.00
	To apply waterproof sealant on affected areas.		150.00
	To apply putty & spray painting on affected areas.		1,350.00
	To remove carpet. Trimming and seat to enable repair.		150.00
	To repait rear windscreen glass.		160.00
	To install reverse sensors.		80.00
	To carry out exhaust work.		80.00
	Total		14,022.53

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

LOW CHEE SENG

Date: 28-12-24

[illegible]