A-Tec Automotive Pte Ltd 8 Kaki Bukit Ave 4 #04-20 Premier Singapore 415875

11 Dec 2024

GBL 7195 M NISSAN NV350

				Estimated	
No	Qty	Parts Description		Parts Price	
1	1	Front headlamp -LH / Cut		\$	959.00
2	1	Front grille logo ?		\$	130.20
3	1	Front grille with chrome assy ?		\$	566.75
4	1	Front bumper / BR		\$	892.70
5	1	Front bumper centre grille X nn		\$	233.30
6	1	Front bumper side bracket / BR		\$	105.00
7	1	Front bumper fog lamp cover / Cut		\$	180.80
8	1	Front bumper reinforcement X nn		\$	667.30
9	1	Front bumper side retainer X nn		\$	50.10
10	1	Front bumper tow hook cover X nn		\$	48.00
11	1	Front wheel rim -LH X nn		\$	500.00
12	1	Front door -LH / DD		\$	1,355.80
13	1	Front door checker X nn		\$	39.70
14	2	Front door hinges X nn		\$	119.80
15	1	Front door rubber X nn		\$	244.30
16	1	Front step garnish / BR		\$	220.30
17	1	Front step panel X nn		\$	488.80
				\$	6,801.85
		nine ell coolen cover / DD	less 10%	\$	680.19
Engine oil cooler cover / BR				\$	6,121.67

No	Qty	Parts Description	Estimated Parts Price		
		Special Nett Items			
1	1	Front grille clip (1 set) ?	\$	60.00	
2	1	Front bumper clip (1 set) / Nec	\$	60.00 30)
3	1	Front tyre X nn	\$	400.00	
4	1	Front door lettering / Nec	\$	45.00 /	
			\$	565.00	

Total parts: \$ 6,686.67

		Labour	
No	Description	Charges	
1	To check wiring, lighting and resetting headlamps	\$ 80.00	30
	focusing.		
2	To conduct wheel alignment.	\$ 150.00	X
3	To remove and refit doors complete fittings and	\$ 200.00	50
	replace damaged parts, transfer all fittings to new		
	door.		
4	To apply undercoating on repaired and replaced	\$ 100.00	20
	panel.		
5	To provide labour charges, workmanship to dismantle	\$ 1,500.00	400
	above damaged parts, repair including cut and weld;		
	re-align body structure and damaged consistent to the		
	accident.		
6	To respray painting include polishing and waxing on	\$ 1,400.00	400
	the changed body parts, repaired portions where		
	consistent to the accident.		_
	Total labour :	\$ 3,430.00	_
	Total parts:	\$ 6,686.67	
	Total labour :	\$ 3,430.00	_
	Total repair cost:	\$ 10,116.67	= _
	Steve (LKK)		_

Steve (LKK) 12/12/24, 10.30am Without Prejudice L/S Resurvey After Spray 4 days