

REF: CS3/SMO24120174/Anh3 (SLU 6413A)

ASSIGNMENT

Front: _____ Date: _____
 Est: _____
 OD / TP / RES / CD RES / EVA / INV / MV
 To in _____ Vehicle No: _____
 at _____
 of _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____
 (Policy Condition)

N/S	O/S

Remark: Vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU6413A Yr Regn: 2017, Dec.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai Elantra C.D. 1591
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 195962 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMHD841CMJU591399
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /
 TOYO / YOKO or Kapsen

Front: _____ Rear: _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 17/14/24

Survey held at New Zen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front n/s, u/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Sampo P.R.S.</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes ()</u>
	<u>1st Survey : No ()</u>
	<u>MV : 40K</u>
	<u>PV : 20.8K</u>
	<u>Nett: 19.2K</u>
	<u>repair range \$4000-\$5000 and 6 days</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: _____

1) _____
 Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS. \$1 _____

Photos _____

Others _____

Report Format: _____

Report Form / P.R. / C.R.



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	NEW ZEN WERKZ	DATE	Dec 16, 2024 12:41:06 PM
FIRST NAME			
LICENSE NO.	SLU 6413 A		
MILEAGE	195960		
MAKE	CUSTOM	MODEL	HYUNDAI ELANTRA (D84)
NOTES			

Front Wheel

SPECS

DIAGNOSIS

ADJUSTMEN

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.00			-9.90				-10.00		
PARTIAL TOE	-0.50	0.00	0.50		-5.90		-4.00		-9.90		0.00	
SET BACK	---	---	---			-0°24"				-0°24"		
CAMBER	-1°14"	-0°30"	0°14"		-2°04"		-1°14" 0°50"		-2°02"		-1°18" 0°44"	
CASTER	3°30"	4°30"	5°30"		4°36"		4°18" 0°16"		4°36"		4°18" 0°16"	
KING-PIN	---	---	---		12°22"		13°40" 1°16"		12°22"		13°40" 1°16"	
INCL ANGLE	---	---	---		10°16"		12°24"		10°20"		12°22"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel

SPECS

DIAGNOSIS

ADJUSTMEN

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	---	---	---			2.20				2.20		
PARTIAL TOE	---	---	---		2.10		0.10		2.10		0.10	
SET BACK	---	---	---			0°12"				0°12"		
CAMBER	---	---	---		-0°52"		-1°04" 0°12"		-0°52"		-1°04" 0°12"	
THRUST ANGLE	-0°08"	0.00	0°08"			0°08"				0°08"		