

ASS. REC. BY:

T. J. J. J.

REF:

CS/ALG 2407 0015/Tvh3

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

fba

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.

☒	
N/S	O/S

Bal. or Market Value:

\$250K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

George

Veh No:

SMY1959S

Yr Regn:

2023 02

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi E-Tron

c.c

287kw

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

7589

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WA4222 GEX2B 017967

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: ☒ Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

255/50R20

R:

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

4/7/24

Survey held at

Premium Alexandra

Des. of Damages: ☒ Front / ☒ Rear / O/S / N/S / U/G / Rooftop or

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:


Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Rep. Format:

Lump Sum / L.B.R. (\$

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0518/2024/KS
DATE : 2-Jul-24
WIP : 21269

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 4/7/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. DAMJANOVIC ROBERT RADA
ADDRESS : BLK 62 HAVELOAD ROAD
#02-21
SINGAPORE 169659
TELEPHONE : HP +65 96356187
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7230015594-01
VEHICLE NO : **SMY 1959 S**
MODEL CODE : AUDI E-TRON SPORTBACK ADV
MODEL YEAR : 16/2/2023
ENGINE NO : EAS188218
CHASSIS NO : WAUZZZGEXPB017967
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Jun-24
PLACE OF ACCIDENT : RIVER VALLEY (BRIGHTON MONTESSORI)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMY 1959 S.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS AND HEADLIGHT, HORNS OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND REINSTALL AIRCON CONDENSOR, RADIATOR AND ADDITIONAL RADIATOR, CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,800.00	✓
3	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	✓
4	TO REINSTALL FRONT BUMPER, TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,500.00	2400 A 2200
5	TO RESPRAY FRONT BUMPER SPOILER AND BOTH WHEEL ARCH TRIMS.	\$ 200.00	300
6	TO CARRY OUT DE-ENERGENISING HIGH VOLTAGE SYSTEM. DEACTIVATION AND ACTIVATION.	S/N \$ 480.00	✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00	✓
TOTAL LABOUR CHARGES		: \$ 8,952.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 1959 S.

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRT BUMPER IMPACT PROTECTION - SELENITE SILVER	1	\$ 1,011.00	fn ✓
2	FRONT BUMPER SPOILER - LH / RH	2	\$ 392.00	X
3	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 318.00	X
4	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 263.00	mis ✓
5	FRONT PLASTIC FOAM STRIP	1	\$ 151.00	?
6	FRONT BUMPER TRIM - LH / RH	2	\$ 146.00	X
7	FRONT BUMPER SPOILER - LH / RH FRONT	2	\$ 238.00	X
8	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 664.00	X
9	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 112.00	X
10	FRONT ENGINE UNDERSHIELD	1	\$ 801.00	X
11	FRONT ENGINE UNDERSHIELD FIXING PARTS	1	\$ 343.00	X
12	FRONT AIR GUIDE - LOWER REAR	1	\$ 85.00	?
13	FRONT CROSS MEMBER	1	\$ 521.00	X
14	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 1,382.00	? plus to.
15	A/C HOSE	1	\$ 248.00	X
16	A/C HOSE	1	\$ 187.00	X
17	A/C HOSE	1	\$ 311.00	X
18	A/C HOSE	1	\$ 252.00	X
19	HEAT EXCHANGER	1	\$ 539.00	X
20	HEAT EXCHANGER WITH REFRIGENT RECEIVER	1	\$ 574.00	X
SUB TOTAL SPARE PARTS		:	\$ 8,538.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 1959 S.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT SIDE MEMBER - LH / RH	2	\$ 504.00	X
22	FRONT LOCK CARRIER	1	\$ 1,443.00	OK ✓
23	FRONT BUMPER ADAPTOR - LH / RH	2	\$ 114.00	X
24	RADIATOR COOLANT	6	\$ 332.00	OK ✓
25	RADIATOR AIR GUIDE - LOWER	1	\$ 53.00	X
26	RADIATOR AIR GUIDE - LOWER FRONT	1	\$ 85.00	X
27	SUNDRIES		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 11,569.00	
TOTAL LABOUR CHARGES		:	\$ 8,952.00	
GRAND TOTAL		:	\$ 20,521.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.


LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanfiah 97495749 4 days
4/7/24 @ 215p-
Not Authorise Ex: to be advise
p/p Resurvey new parts / old parts
tanfiah @kkhauto.com

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT