

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: 39 WOODLANDS CLOSE, #01-12 MEGA@WOODLANDS S(737856)

DID: 6256 2081 / 6256 2210

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

DID: 6702 3113 (3Lines)

Branch: 60 Jalan Lam Huat Carros Centre #01-31/32 S(737869)

DID: 6592 1522 / 6592 7822

ROC: 200311009C GST: 200311009C

Website: <https://www.yewteegroup.com/> Email: claims@yewteegroup.com

ON BEHALF OF OWNER :

Policy Particulars: - OWN DAMAGED CLAIM

Insured veh.	SNH3106B	Excess.	\$ 700.00
Policy No.	MOMVP000005732-00-000	Coverage.	Comprehensive
Claiming Against.			
Insured Under.	GREAT AMERICAN		

Vehicle Particulars & Condition

Make & Model	MERC C200
Engine No.	13556146B58B30C
Chassis No.	WBACR620709E36732
Odometer	
Engine CC.	
Year Of Reg.	2020
Colour.	BLACK
Parf/COE Rebate.	\$ 121,140.00

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

Front portion damaged.

General Information

Accident Date. 09/12/2024
Survey held at

Yew Tee Automobile Tech Pte Ltd
KAKI BUKIT ROAD 4 #01-61 S(417800)

25

Remarks

**A) THE SURVEY WAS CONDUCTED ON A "PBP / LUMPSUM" BASIS
KINDLY LET US HAVE THE APPROVAL SOON.**

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: 10 Days

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: 39 WOODLANDS CLOSE, #01-12 MEGA@WOODLANDS S(737856)

DID: 6256 2081 / 6256 2210

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

DID: 6702 3113 (3Lines)

Branch: 60 Jalan Lam Huat Carros Centre #01-31/32 S(737869)

DID: 6592 1522 / 6592 7822

ROC: 200311009C GST: 200311009C

Website: <https://www.yewteegroup.com/> Email: claims@yewteegroup.com

ON BEHALF OF OWNER :

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
1	BONNET	\$ 2,800.00
1	BONNET LOGO	\$ 140.00
1	FRT GRILLE CHROME	\$ 400.00
1	FRT GRILLE BACKING	\$ 580.00
1	FRT GRILLE CAMERA	\$ 800.00
1	FRT NUMBER PLATE BASE	\$ 70.00
1	FRT HEADLAMP LH	\$ 4,000.00
1	FRT HEADLAMP RH	\$ 4,000.00
1	FRT BUMPER	\$ 1,600.00
1	FRT BUMPER BRACKET LH	\$ 300.00
1	FRT BUMPER BRACKET RH	\$ 300.00
1	FRT BUMPER INNER SPONGE	\$ 200.00
1	FRT BUMPER REINFORCEMENT	\$ 400.00
1	FRT BUMPER INNER AIR GUIDE LOWER	\$ 380.00
1	FRT BUMPER INNER AIR GUIDE UPPER	\$ 350.00
1	FRT HEADLAMP LOWER BRACKET LH	\$ 220.00
1	FRT HEADLAMP LOWER BRACKET RH	\$ 220.00
1	FRT BUMPER CENTRE LOWER AIR GRILLE	\$ 160.00
1	FRT BUMPER CENTRE LOWER AIR GUIDE LH	\$ 270.00
1	FRT BUMPER CENTRE LOWER AIR GUIDE RH	\$ 270.00
1	RADAR UNIT	\$ 3,200.00

Parts	\$ 20,660.00
Less 10%	\$ 2,066.00
Sub	\$ 18,594.00

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: 39 WOODLANDS CLOSE, #01-12 MEGA@WOODLANDS S(737856)

DID: 6256 2081 / 6256 2210

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

DID: 6702 3113 (3Lines)

Branch: 60 Jalan Lam Huat Carros Centre #01-31/32 S(737869)

DID: 6592 1522 / 6592 7822

ROC: 200311009C GST: 200311009C

Website: <https://www.yewteegroup.com/> Email: claims@yewteegroup.com

ON BEHALF OF OWNER :

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
1	FRT NUMBER PLATE	\$ 40.00
1	FRT BUMPER SENSOR SET	\$ 1,000.00

S/N \$ 1,040.00

LABOUR

To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts. \$ 200.00

To programming & coding for Radar unit \$ 580.00

To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools. \$ 1,000.00

To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available. \$ 700.00

LABOUR \$ 2,480.00

Sub Total. \$ 22,114.00

9% GST \$ 1,990.26

Grand Total \$ 24,104.26

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.