

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: 39 WOODLANDS CLOSE, #01-12 MEGA@WOODLANDS S(737856)

DID: 6256 2081 / 6256 2210

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

DID: 6702 3113 (3Lines)

Branch: 60 Jalan Lam Huat Carros Centre #01-31/32 S(737869)

DID: 6592 1522 / 6592 7822

ROC: 200311009C GST: 200311009C

Website: <https://www.yewteegroup.com/> Email: claims@yewteegroup.com

ON BEHALF OF OWNER :

Policy Particulars: - OWN DAMAGED CLAIM

Insured veh.	SNH3106B	Excess.	\$ 700.00
Policy No.	MOMVP000005732-00-000	Coverage.	Comprehensive
Claiming Against.			
Insured Under.	GREAT AMERICAN		

Vehicle Particulars & Condition

Make & Model	MERCEDES BMW X5
Engine No.	13556146B58B30C
Chassis No.	WBACR620709E36732
Odometer	
Engine CC.	
Year Of Reg.	2020
Colour.	BLACK
Part/COE Rebate.	\$ 121,140.00

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

Front portion damaged.

General Information

Accident Date. 09/12/2024
Survey held at

Yew Tee Automobile Tech Pte Ltd
KAKI BUKIT ROAD 4 #01-61 S(417800)

25

Remarks

A) THE SURVEY WAS CONDUCTED ON A "PBP / LUMPSUM" BASIS
KINDLY LET US HAVE THE APPROVAL SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: 10 Days

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: 39 WOODLANDS CLOSE, #01-12 MEGA@WOODLANDS S(737856)

DID: 6256 2081 / 6256 2210

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

DID: 6702 3113 (3Lines)

Branch: 60 Jalan Lam Huat Carros Centre #01-31/32 S(737869)

DID: 6592 1522 / 6592 7822

ROC: 200311009C GST: 200311009C

Website: <https://www.yewteegroup.com/> Email: claims@yewteegroup.com

ON BEHALF OF OWNER :

Qty.	Description Of Parts	Pricing
1	BONNET X	\$ 2,000.00
1	BONNET LOGO X	\$ 140.00
1	FRT GRILLE CHROME / BR BR (Bwt)	\$ 400.00 280.00
1	FRT GRILLE BACKING	\$ 580.00 480.00
1	FRT GRILLE CAMERA X	\$ 800.00
1	FRT NUMBER PLATE BASE / BR	\$ 70.00 85.00
1	FRT HEADLAMP LH X	\$ 4,000.00
1	FRT HEADLAMP RH X	\$ 1,000.00
1	FRT BUMPER / DEF	\$ 1,600.00 1900.00
1	FRT BUMPER BRACKET LH X	\$ 300.00
1	FRT BUMPER BRACKET RH X	\$ 300.00
1	FRT BUMPER INNER SPONGE X	\$ 200.00
1	FRT BUMPER REINFORCEMENT X	\$ 400.00
1	FRT BUMPER INNER AIR GUIDE LOWER X	\$ 300.00
1	FRT BUMPER INNER AIR GUIDE UPPER / BR	\$ 350.00 125.00
1	FRT HEADLAMP LOWER BRACKET LH X	\$ 220.00
1	FRT HEADLAMP LOWER BRACKET RH X	\$ 220.00
1	FRT BUMPER CENTRE LOWER AIR GRILLE / BR	\$ 160.00 125.00
1	FRT BUMPER CENTRE LOWER AIR GUIDE LH X	\$ 270.00
1	FRT BUMPER CENTRE LOWER AIR GUIDE RH X	\$ 270.00
1	RADAR UNIT X	\$ 3,200.00

Parts	\$ 20,000.00	2,995.00
Less 10%	\$ 2,000.00	+10%
Sub	\$ 18,504.00	Parts: 3,294.50

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: 39 WOODLANDS CLOSE, #01-12 MEGA@WOODLANDS S(737856)

DID: 6256 2081 / 6256 2210

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

DID: 6702 3113 (3Lines)

Branch: 60 Jalan Lam Huat Carros Centre #01-31/32 S(737869)

DID: 6592 1522 / 6592 7822

ROC: 200311009C GST: 200311009C

Website: <https://www.yewteegroup.com/> Email: claims@yewteegroup.com

ON BEHALF OF OWNER :

Qty.	Description Of Parts	Pricing
1	FRT NUMBER PLATE ✓ BT	\$ 40.00 40.00
1	FRT BUMPER SENSOR SET	\$ 1,888.00

S/N ~~\$ 1,840.00~~ 40.00

LABOUR

To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.

\$ 200.00 100 100.00

~~To programming & coding for Radar unit~~

~~\$ 388.00~~

To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.

\$ 1,000.00 250 250.00

To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.

\$ 700.00 220 220.00

M Bnp ✓

LABOUR ~~\$ 2,488.00~~ Labour: 610.00

Steve (LKK)

17/12/24, 2.20pm

Waste DD-AL1 AvL

EXH 11 - ?

PIP

W BOC M
3 days

Sub Total. \$ 22,114.00
9% GST \$ 1,990.26
Grand Total \$ 24,104.26

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

YEW TEE AUTOMOBILE TECH PTE LTD

39 WOODLANDS CLOSE #01-12 MEGA@WOODLANDS S(737856)
25 KAKI BUKIT ROAD 4 #01-61 SYNERGY@KB S(417800)
60 JALAN LAM HUAT CARROS CENTRE #01-31/32 S(737869)

To: GREAT AMERICAN INSURANCE COMPANY

DATE: 31.12.2024

Dear Sir / Madam:

RE: VEHICLE REPAIR ESTIMATE SUPPLEMENTARY

Owner : CALMO HOTEL PTE. LTD.

Model : BMW X5

Reg : SNH3106B

Chassis : WBACR62U/U9E36/32

DOAccident : 09.12.2024

OWN DAMAGED CLAIM AGAINST

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	FRONT BUMPER CENTER TRIM	\$ 400.00	400.00 /

Total Parts :	\$	400.00	400.00
Less	10%	\$ 40.00	+10%
		\$ 360.00	440.00

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

Shaun : 97432262

Steve (LRT)
2/1/24, 3:30pm

Parts: \$3,294.50

S/N Item: \$40.00

Labour: \$610.00

Supplementary Parts: \$440.00

Total: \$4,384.50

