

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: 39 WOODLANDS CLOSE, #01-12 MEGA@WOODLANDS S(737856)

DID: 6256 2081 / 6256 2210

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

DID: 6702 3113 (3Lines)

Branch: 60 Jalan Lam Huat Carros Centre #01-31/32 S(737869)

DID: 6592 1522 / 6592 7822

ROC: 200311009C GST: 200311009C

Website: <https://www.yewteegroup.com/> Email: claims@yewteegroup.com

ON BEHALF OF OWNER :

Qty.	Description Of Parts	Pricing
1	FRT NUMBER PLATE ✓ BT	\$ 40.00 40.00
1	FRT BUMPER SENSOR SET	\$ 1,888.00

S/N ~~\$ 1,840.00~~ 40.00

LABOUR

To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.

\$ 200.00 100 100.00

~~To programming & coding for Radar unit~~

~~\$ 388.00~~

To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.

\$ 1,000.00 250 250.00

To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.

\$ 700.00 220 220.00

M Bnp ✓

LABOUR ~~\$ 2,488.00~~ Labour: 610.00

Steve (LKK)

17/12/24, 2.20pm

Waste DD-AL1 AvL

EX-11-1

PIP

By BOC 14
3 days

Sub Total. \$ 22,114.00
9% GST \$ 1,990.26
Grand Total \$ 24,104.26

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.