

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/12/2024
TP Veh Reg No: SLT6757M

Estimate No: EST2400492
Date: 12 Dec 2024

Veh Reg No: SND2098T
Make/Model: TOYOTA AXIO 1.5EX
MANUAL

Chasis No: NZE1617133902
Reg. Date: 14/12/2021
Your Ref No: SLT6757M

Estimate Repair Cost to Vehicle No :SND2098T

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID	1,417.00	
2	1 PC BOOT LID LOGO	64.09	
3	1 PC BOOTLID "COROLLA" EMBLEM	61.80	
4	1 PC BOOTLID "AXIO" EMBLEM	68.89	
5	2 PCS BOOT LID HINGE	310.80	
6	1 PC BOOT LID RUBBER	293.65	
7	1 PC BOOT LID LOCK	602.88	
8	1 PC BOOT LID LOCK CHECKER	41.40	
9	1 PC BOOT LID TRIM	230.30	
10	1 PC REAR PANEL	1,154.20	
11	1 PC REAR PANEL TRIM	374.40	
12	1 PC TAIL LAMP LH	955.90	
13	1 PC TAIL LAMP PANEL LH	161.30	
14	1 PC TAIL LAMP - RH	955.90	
15	1 PC REAR BUMPER	843.90	
16	2 PCS REAR BUMPER SIDE RETAINER	334.64	
17	2 PCS REAR BUMPER SMALL RETAINER	201.80	
18	1 PC REAR LH FENDER TRIM	456.90	
19	1 PC REAR SPARE TYRE HARDBOARD	559.30	
20	1 PC REAR BUMPER REFLECTOR - LH	141.59	
		9,230.64	
		Less 25%	2,307.66
			6,923.02
	Special Net		
21	1 SET BOOTLID TRIM CLIPS	40.00	
22	1 PC BOOT LID NUMBER '719' STICKER	55.00	
23	1 SET REAR PANEL TRIM CLIPS	40.00	
24	2 PCS "L" PLATE BRACKET	80.00	
25	1 SET REAR BUMPER STICKER	280.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/12/2024
TP Veh Reg No: SLT6757M

Estimate No: EST2400492
Date: 12 Dec 2024

Veh Reg No: SND2098T
Make/Model: TOYOTA AXIO 1.5EX
MANUAL

Chasis No: NZE1617133902
Reg. Date: 14/12/2021
Your Ref No: SLT6757M

Estimate Repair Cost to Vehicle No :SND2098T

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
26	1 SET REAR BUMPER CLIPS	60.00	
27	1 SET REAR FENDER TRIM CLIPS LH	60.00	
		615.00	615.00
	Labour		
28	1 TO CHECK WIRING	50.00	
29	1 TO REPLACE STICKER	80.00	
30	1 TO REMOVE AND REFIT INNER TRIM	150.00	
31	1 TO SPRAY UNDERSEAL	100.00	
32	1 (REAR) TO SPRAY PAINTING	1,200.00	
33	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	
		2,780.00	2,780.00
		Total	S\$ 10,318.02
		Add GST @ 9%	928.62
		Total Amount Payable	<u>S\$ 11,246.64</u>

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND TWO HUNDRED FORTY SIX AND CENTS SIXTY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE