

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

MSIG Insurance (Singapore) Pte Ltd

4 Shenton Way

#21-01 SGX Centre 2

Singapore 068807

Attention : Motor Claim Department

Contact : 68277888 Fax No. : 62257402

Hui Rong

Estimate : TP24-063

Date : 01/07/2024

Vehicle Num. : SKS8653H

Make/Model : Mercedes CLA180-2015

Chassis/Eng# : WDD1173422N196545/27091030626168

Accident Date : 25/06/2024

Claim No. :

Reference :

Policy No. : 11428709

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	Rear Bumper Assy		1,630.00 ✓
3.	1	Rear Lower Bumper		485.00 ✓
4.	1	Rear bumper chrome trim assy		590.00 +
5.	2	Rear Bumper Bracket L/R		316.00 +
6.	1	Rear Bumper Reinforcement		780.00 +
7.	1	Rear PDC parking sensor		235.00 +

List Total S\$:

10.00% Discount S\$:

4,036.00

403.60

3,632.40

1.	10	SPECIAL NETT ITEMS :		
		Rear Bumper Clips	15.00	150.00 ✓ 50
		Special Nett Total S\$:		150.00

LABOUR :

To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident

To putty and respray painting on rear bumper and rear boot lid.

Labour Total S\$:

600.00 ✓ 200

800.00 ✓ 200

1,400.00

Total S\$: 5,182.40

=====

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling
1/5 02/07/24
22 Day
Total: 2353.50
1/5: 1850 ✓